LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. From: LKK Auto Consultants Pte Ltd

6 Temasek Boulevard 51 Ubi Ave 1 #01-25 #18-01 Suntec Tower 4 Paya Ubi Industrial Park Singapore 038986 Singapore 408933

Lionel Tan Date: 04 Jul 2022 Attn:

Preliminary Advice

Vehicle No : SDW4323Z Accident Date : 26/06/2022 Make : HONDA VEZEL Policy No. : PNPV2020-00000904-01

Assignment Date : 28/06/2022 **Excess** : S\$750.00

Date of Inspection : 30/06/2022 Est. Duration of Repair

Inspection At : PROGRESSIVE CAR CARE PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

TOTAL LOSS Repairer's Estimate (Gross) :S\$ **Revised Amount TOTAL LOSS** :S\$

Check Items (Estimated) :S\$ Total :S\$

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 54,000.00 COE / PARF Rebate :S\$ 25,546.00

Salvage Value :S\$

Margin for Repair :S\$ 28,454.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	ylk
		let us have your authorisation.	

- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: Vehicle pending for investigation. (X)