



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD 6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986			Ref: CS4/FWD22006148/Ncy3 Date: 28/06/2022 Code: FWD	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SDW 4323Z
	Policy No.	PNPV2020-00000904-01	Coverage (\$)	0.00
	Claim No.	1202200013021	Excess (\$)	750.00
	Assign From	LIONEL TAN	Assign Date	28/06/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	26/06/2022	Inspection Date	29/06/2022
	Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		
5a. Remarks				
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			