

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 13 Oct 2022

## **Preliminary Advice**

Insured Vehicle No : YM6079U

TP Vehicle No : SG6192C

Make : MAN A95

Date of Inspection : 28/06/2022

Inspection At : SBS TRANSIT LTD

Accident Date : 23/06/2022

Assignment Date : 04/07/2022

Est. Duration of Repair : 01 DAYS

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 1,367.00 |
| Revised Amount              | :S\$ | 1,367.00 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 1,367.00 |

Lump Sum Repair :S\$

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a 'Without Prejudice' basis.  
Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.