

Date: 28/06/2022
Vehicle No: SNB184B
Model: TOYOTA PRIUS 5DR HATCHBACK
Chassis: JTDKB3FU003091946-2020
Reg.Year: 2021

*Not Authorized
L/P 271.50*

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SMJ4877D
Date of Accident: 26/06/2022
Estimator: TING AN
Surveyor:

Penyany After Pain

7 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR TAILGATE	1	R	\$1,238.00	X
2	REAR TAILGATE OUTER GARNISH COVER	1	M/C M	\$891.00	X
3	REAR TAILGATE "PRIUS" EMBLEM	1	R	\$75.00	-
4	REAR TAILGATE "HYBRID" EMBLEM	1	R	\$75.00	-
5	REAR TAILGATE INNER TRIM BOARD	1	R	\$251.00	X
6	REAR TAILGATE INNER LOCK	1	R	\$452.00	X
7	REAR TAILGATE WEATHERSTRIP	1	R	\$360.00	X
8	REAR SPOILER	1	R	\$1,245.00	X
9	REAR WINDSCREEN MOULDING	1	R	\$95.00	X
10	REAR TAILGATE LAMP RH	1	CM	\$256.00	-
11	REAR UPPER TAIL LAMP RH	1	CM	\$433.00	-
12	REAR LOWER TAIL LAMP RH	1	CM	\$486.00	-
13	REAR BUMPER	1	R	\$488.00	-
14	REAR BUMPER LOWER LIP <i>374.50</i>	1	R	\$486.00	-
15	REAR BUMPER REFLECTOR RH	1	PER	\$60.00	-
16	REAR BUMPER SIDE BRACKET RH	1	DI	\$112.00	-
17	REAR BUMPER REINFORCEMENT <i>318.80</i>	1	R	\$336.00	-
18	REAR BUMPER ANTENNA SENSOR	1	R	\$75.00	X
19	REAR BUMPER TOWING COVER	1	MIT	\$25.00	-
20	REAR END PANEL	1	R	\$729.00	X
21	REAR END PANEL UPPER COVER	1	M/C M	\$155.00	X
22	REAR FLOOR PANEL TOOLBOX TRAY	1	R	\$165.00	X
23	REAR FLOOR PANEL TOOLBOX TRAY UPPER BOARD	1	R	\$504.00	X
24	FRONT BONNET <i>950.50</i>	1	R	\$993.00	-
25	FRONT HEADLAMP RH <i>2637.60</i>	1	M/C M	\$3,052.00	-
26	FRONT BUMPER <i>499.90</i>	1	R	\$565.00	-
27	FRONT BUMPER TOWING COVER RH	1	DEL	\$95.00	-
28	FRONT BUMPER SIDE BRACKET RH	1	DI	\$85.00	-
29	FRONT BUMPER GARNISH COVER RH	1	R	\$172.00	X
30	FRONT BUMPER LOWER GRILLE	1	R	\$202.00	X
31	FRONT BUMPER REINFORCEMENT	1	R	\$691.00	X
32	FRONT BUMPER ABSORBER FOAM	1	CM	\$135.00	X
33	FRONT GRILLE <i>321.90</i>	1	DI/DEL	\$457.00	-
34	FRONT FENDER RH	1	R	\$988.00	X

Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg /OptimaWerkz

ASS. REC. BY: Kenneth
REF: ASM/2200622.11
Date: 28/06/2022
Vehicle No: SNB184B
Model: TOYOTA PRIUS 5DR HATCHBACK
Chassis: JTDKB3FU003091946-2020
Reg. Year: 2021

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SMJ4877D
Date of Accident: 26/06/2022
Estimator: TING AN
Surveyor:

35	FRONT FENDER "HYBRID" EMBLEM RH	1		nn \$55.00	X
36	REAR FENDER RH	1		REPAIR	
SUB TOTAL				\$16,482.00	
LESS 25%				-\$4,120.50	
PARTS TOTAL				\$12,361.50	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	REAR WINDSCREEN SEALANT	1		nn \$80.00	X
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		nn \$50.00	X
3	REAR BUMPER CLIPS	1		nn \$50.00	
4	REAR BUMPER REVERSE SENSOR	1		not \$300.00	2001n
5	REAR END PANEL JOINT SEALANT	1		nn \$100.00	X
6	REAR END PANEL UPPER COVER CLIPS	1		nn \$40.00	X
7	REAR BUMPER RUBBER MAT	1		nn \$80.00	301n
8	FRONT GRILLE CLIPS	1		nn \$40.00	
9	FRONT NUMBER PLATE & HOLDER	1		By \$50.00	451n
S/N TOTAL				\$790.00	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC. \$2,000.00 900/-

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR TAILGATE OUTER GARNISH COVER, REAR BUMPER, REAR END PANEL, REAR FENDER RH, FRONT BONNET, FRONT BUMPER, FRONT FENDER RH & ETC. \$1,800.00 1200/-

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREE GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE. nn \$150.00 X

LABOUR CHAREGS TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. nn \$120.00 X

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. \$100.00 50/-

Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



ASS. REC. BY: *Kenneth*

REF: *Asm/2200638, 11-*

From:

OPTIMA WERKZ™ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg /OptimaWerkz

Date: 28/06/2022
Vehicle No: SNB184B
Model: TOYOTA PRIUS 5DR HATCHBACK
Chassis: JTDKB3FU003091946-2020
Reg. Year: 2021

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SMJ4877D
Date of Accident: 26/06/2022
Estimator: TING AN
Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00	<i>3ol</i>
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$120.00	<i>nn x</i>
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$100.00	<i>4ol</i>
	LABOUR TOTAL	\$4,540.00
TING AN	TOTAL	\$17,691.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

