

ASS. REG. BY:

REF:

CS/SPF 22 006154/TCY 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Ms. Lane

Veh No:

SH 9192C

Yr Regn:

2019 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

391729

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

STDKRB3FU 903078984

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

29/6/22

Survey held at

Garage Loggia

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format:

Lump Sum / L.B.L. (%)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH9192C

Make : Toyota

Model : Prius

Date: 24/06/2022

Insurance: *SPP Veh.*

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$ 586.18 <i>ke</i>
1	FRONT BUMPER FOG LAMP			\$ 920.00 <i>X</i>
10	FRONT BUMPER CLIPS			\$ 22.00 <i>ke</i>
1	FRONT BUMPER SIDE BRACKET RH			\$ 82.30 <i>ke</i>
1	HEAD LAMP PANEL RH			\$ 240.10 <i>ke</i>
1	HEADLAMP RH			\$ 2,735.28 <i>3</i>
1	FRT FENDER EMBLEM RH			\$ 86.50 <i>ke</i>
	SUB TOTAL			\$ 4,672.36
	LESS 25%			\$ 1,168.09
	DISCOUNTED TOTAL			\$ 3,504.27
				\$ -
	Labour Charge			
	PANEL BEATING			\$ 750.00 <i>350</i>
	SPRAY PAINTING CHARGE			\$ 600.00 <i>500</i>
	CHECK ALL LIGHTING			\$ 50.00 <i>30</i>
	TOTAL LABOUR			\$ 1,400.00
	ESTIMATE TOTAL			\$ 4,904.27

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 47413745
up 24/6/22 @ 550
L/S Perry after repair
2 days
Tanpin C. M. Anderson

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 24.06.2022 08:23

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305520756

STOMER

REGN NO: SH 9192C

MILEAGE

/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045

MAKE: TOYOTA

FUEL

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (R) (O)
(P)

MODEL PRIUS HYBRID(G4)23.06.2022 14:20

DATE/TIME IN

YR OF MANU 14.03.2019

TARGET DATE

CHASSIS CODE JTDKB3FU903078984

COMPLETION DATE/TIME:

COUNT CARD NO.


JOB DESCRIPTION

Accident Date: 22.06.2022
NATURE: 3P 22.06.2022

3/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 9192C

YY

Vehicle No.: SH 9192C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard