



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22006158/Ecy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1			Date:	23/09/2022
HEMMANT ROAD SINGAPORE 438675				
ATTN: HAFIZUL FARHAN			Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 1479T	Veh. Inspected	SJE 2683X	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/037	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	28/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053HY9305057802	Colour	SILVER	
Odometer	251950 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	MICHELIN	4 mm	
L/H Front Tyre	195/50 R15	MICHELIN	4 mm	
R/H Rear Tyre	195/50 R15	MICHELIN	4 mm	
L/H Rear Tyre	195/50 R15	MICHELIN	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/05/2022	Inspection Date	30/06/2022	
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	