



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|---|-----------------|---|--|
| AUTOMOTIVE ENGRG. & MGT. DIVISION (TP) ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675 ATTN: HAFIZUL FARHAN | | | Ref: CS/SPF22006160/Rqy3e2 Date: 24/08/2022 Code: SPF | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | TP 461G | Veh. Inspected | SKU 3271Z | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | ACS/105/009/2022/038 | Excess (\$) | 0.00 | |
| Assign From | HAFIZUL FARHAN | Assign Date | 28/06/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA ESTIMA HYBRID 2.4X A | c.c | 2362 | |
| Engine No. | HIDDEN | Year of Reg. | 2010 | |
| Chassis No. | AHR207041052 | Colour | WHITE | |
| Odometer | 125562 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 225/55 R17 | TOYO | 6 mm | |
| L/H Front Tyre | 225/55 R17 | TOYO | 6 mm | |
| R/H Rear Tyre | 225/55 R17 | TOYO | 6 mm | |
| L/H Rear Tyre | 225/55 R17 | TOYO | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 20/05/2022 | Inspection Date | 28/06/2022 | |
| Survey held at | CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 5 Working Days | |