



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2204433

INV Date 20/07/2022

Reference CS/EQI22006163/Ucy3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SMP 5552C

Insured Veh. PUBLIC LIABILITY

Claim No. DL22HO00164/LL

Policy No.

Accident Date 24/06/2022

Inspection Date 30/06/2022

Description	Total
Survey Inspection	160.00
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CS/EQI22006163/Ucy3e2 Date: 20/07/2022 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SMP 5552C	
Policy No.		Coverage (\$)	0.00	
Claim No.	DL22HO00164/LL	Excess (\$)	0.00	
Assign From	LYNN LIM	Assign Date	28/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JM6GL1072K0315541	Colour	BLUE	
Odometer	50729 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	YOKOHAMA	7 mm	
L/H Front Tyre	225/55 R17	YOKOHAMA	7 mm	
R/H Rear Tyre	225/55 R17	YOKOHAMA	7 mm	
L/H Rear Tyre	225/55 R17	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2022	Inspection Date	30/06/2022	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 5552C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	1,099.00	1,099.00
4	TAPE PROTECTOR	NECESSARY	18.80	18.80
2	TAPE SEAL	NECESSARY	27.40	27.40
2	RIVET	NECESSARY	18.40	18.40
1	GASKET RH TAIL LAMP	NECESSARY	46.00	46.00
1	GASKET LH TAIL LAMP	NECESSARY	46.00	46.00
			1,255.60	1,255.60
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER.		800.00	660.00
	TO RESPRAY REAR BUMPER.		700.00	630.00
	TO TRANSFER REVERSE SENSOR.		330.00	180.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTION.		250.00	120.00
	TO REPROGRAMME AFTER REPAIR.		350.00	150.00
			2,430.00	1,740.00
	GRAND TOTAL		3,735.60	2,995.60
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			2,995.60

Report Ref No. CS/EQI22006163/Ucy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 5552C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

