

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22006167/Vvy3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date:	25/08/2022	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SFJ 8008C	Veh. Inspected	SNG 988Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10016063/JM	Excess (\$)	0.00	
	Assign From	MAYBIE CHUA	Assign Date	28/06/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	LAMBORGHINI HURACAN	c.c	5204	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	ZHWEC1ZF4FLA01342	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/30Z R20	PIRELLI	6 mm	
	L/H Front Tyre	245/30Z R20	PIRELLI	6 mm	
	R/H Rear Tyre	245/30Z R20	PIRELLI	6 mm	
	L/H Rear Tyre	245/30Z R20	PIRELLI	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/06/2022	Inspection Date	28/06/2022	
	Survey held at	Survey held at TEAMWORK GARAGE PTE LTD			
		53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

**5 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: