



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI22006169/Tvy3m4

Date: 22/03/2023

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|--------------|-----------------------|------------|
| Insured Veh. | SLJ 145X | Veh. Inspected | SMR 6288Z |
| Policy No. | P10638657R00 | Coverage (\$) | 0.00 |
| Claim No. | C10016044/JM | Excess (\$) | 0.00 |
| Assign From | MAYBIE CHUA | Assign Date | 28/06/2022 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|------------|
| Make & Model | HYUNDAI AVANTE | c.c | 1598 |
| Engine No. | HIDDEN | Year of Reg. | 2021 |
| Chassis No. | KMHLN41ETNU192457 | Colour | WHITE |
| Odometer | 24683 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|------------|---------|---------|
| R/H Front Tyre | 205/55 R16 | HANKOOK | 6 mm |
| L/H Front Tyre | 205/55 R16 | HANKOOK | 6 mm |
| R/H Rear Tyre | 205/55 R16 | HANKOOK | 6 mm |
| L/H Rear Tyre | 205/55 R16 | HANKOOK | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|-----------------------|---|------------------------|------------|
| Accident Date | 24/06/2022 | Inspection Date | 28/06/2022 |
| Survey held at | TSL AUTO GARAGE BLK 1 KAKI BUKIT AVENUE 6 #01-08 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**