

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMR6288Z Hyundai Avante

No	Qty	Parts Description	Estimated Parts Price
			\$ 481,400.00 ✓
1	1	Rear bumper assy	\$ 112.00 LHde ✓ RH X NN
2	2	Rear bumper side retainer	\$ 113.00 LHde ✓ RH X NN
3	2	Rear bumper bracket	\$ ✓ 359.00 cur ✓
4	1	Rear bumper reinforcement	\$ 177.00 X NN
5	1	Rear bumper inner foam	\$ ¹¹⁰ 351.00 cut ✓
6	1	Rear bumper lower cover	\$ ⁹⁰ 124.00 cut ✓
7	1	Rear bumper left lower reflector	\$ 115.00 X NN
8	1	Rear bumper inner garnish	\$ 98.00 X NN
9	1	Rear bumper tow cover	\$ ⁸⁸⁰ 995.00 cur ✓
10	1	Rear left taillamp assy	\$ 995.00 X NN
11	1	Rear right taillamp assy	\$ 863.00 X NN
12	1	Rear centre reflector	\$ 1,416.00 R ✓
13	1	Rear left fender assy	\$ ¹⁴⁵ 224.00 cut ✓
14	1	Rear left fender inner cowl	\$ 321.00 X ✓
15	1	Rear left fender inner garnish	\$ 129.00 X
16	1	Rear bumper left mudflap	\$ 252.00 X
17	1	Rear bootlid lock mechanism	\$ 96.00 X
18	1	Rear bootlid lock catch	\$ 207.00 X
19	1	Rear bootlid lock cylinder	\$ 266.00 X
20	1	Rear bootlid weatherstrip	\$ 289.00 X
21	1	Rear bootlid auto lock switch	\$ 1,230.00 R ✓
22	1	Rear end panel	\$ 211.00 X
23	1	Rear end panel top garnish	\$ 64.00 X } NN
24	1	Rear bootlid inner lamp	\$ 96.00 X
25	2	Rear no plate lamp	\$ 10,503.00
			\$ 2,100.60
		less 20%	\$ 8,402.40

TSL Auto Garage
 Blk 4 Joo Chiat Complex
 #12-1171 Joo Chiat Road
 Singapore 420004

SMR6288Z Hyundai Avante

No	Qty	Parts Description	Estimated Parts Price
		<u>Special Nett Items</u>	
1	10	Rear bumper clips	\$ 60.00 <i>3over</i>
2	1	Rear bumper lower spoiler	\$ 1,250.00 <i>at \$500</i>
3	1	Rear bumper lower spoiler sealant	\$ 100.00 <i>3over</i>
4	10	Rear bumper lower spoiler clips	\$ 50.00 <i>xra</i>
5	4	Rear left fender inner cowling clips	\$ 40.00 <i>2over</i>
6	8	Rear left fender inner garnish clips	\$ 40.00 <i>x</i>
7	10	Rear bumper lower cover clips	\$ 40.00 <i>x</i>
8	1	Rear view camera	\$ 450.00 <i>x</i>
9	1	Rear left quarter garnish sealant	\$ 60.00 <i>x</i>
10	1	Rear windscreen glass sealant	\$ 80.00 <i>x</i>
11	1	Rear bumper reverse sensor	\$ 1,200.00 <i>200w</i>
12	1	Rear no plate with garnish	\$ 100.00 <i>x</i>
13	1	Rear end lower panel sealant	\$ 120.00 <i>x</i>
14	4	Rear end lower panel top garnish clips	\$ 30.00 <i>x</i>
			<hr/> \$ 3,620.00
		Total parts	\$ 12,022.40

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMR6288Z Hyundai Avante

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,000.00 600
2	To putty and spray painting rear portion.	\$ 1,000.00 700
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear bootlid lock mechanism.	\$ 80.00 X
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00 60
6	To apply anti rust proofing to rear affected area.	\$ 120.00 30
7	To remove and install rear fuel tank to facilitate the repair.	\$ 150.00 X un
8	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 X un
9	To remove and install rear left quarter garnish.	\$ 100.00 X un
10	To remove and install rear bumper reverse sensor.	\$ 80.00 30 un
11	To remove and install rear view camera.	\$ 80.00 X
12	Towing service.	\$ 100.00 X
Total labour :		\$ 3,050.00

Total parts : \$ 12,022.40
Total labour : \$ 3,050.00
Total repair cost : \$ 15,072.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 97495749
 wp' 28/6/22 e 11am
 05 days
 US Resurvey after repair
 Tanpin 2/11/2022