

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 8601Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER SIDE COVER RH	TO REPAIR SEE LABOUR	195.00	-
1	REAR BUMPER SIDE COVER RETAINER RH	NOT REQUIRED	28.00	-
1	REAR RH FENDER	TO REPAIR SEE LABOUR	950.20	-
1	REAR RH FENDER ARCH PROTECTOR	SCRAPED	210.00	210.00
10	REAR RH FENDER ARCH PROTECTOR CLIP	NECESSARY	39.00	39.00
1	REAR RH DOOR ASSY	TO REPAIR SEE LABOUR	901.20	-
1	REAR RH DOOR GLASS REGULATOR C/MOTOR	SERVICEABLE	390.20	-
1	FRONT RH DOOR ASSY	TO REPAIR SEE LABOUR	950.10	-
	LESS 20% DISCOUNT		-732.74	-49.80
			2,930.96	199.20
	LABOUR			
	LABOUR CHARGES TO REMOVE AND REPLACE DAMAGED PARTS, TO CUT AND WELD DAMAGED BODY PANELS, TO KNOCK AND RESHAPE AFFECTED AREAS, TO ADJUST AND ALIGN MISALIGNED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE COVER RH, REAR RH FENDER, REAR RH DOOR ASSY AND FRONT RH DOOR ASSY. INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE COVER RH, REAR RH FENDER, REAR RH DOOR ASSY AND FRONT RH DOOR ASSY AND FRONT RH DOOR ASSY.		750.00	500.00
	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY PAINT THE REAR BUMPER, REAR RH FENDER, REAR RH DOOR, FRONT RH DOOR AND NECESSARY AREAS.		1,250.00	1,000.00
	TO CHECK WIRING AND REPAIR WHERE NEEDED.		45.00	30.00
	TO REMOVE AND TRANSFER DOOR GLASS AND FITTINGS.	NOT NECESSARY	90.00	-
	TO APPLY ANTI-RUST UNDERCOAT FOR THE AFFECTED AREAS.		150.00	50.00
			2,285.00	1,580.00
	GRAND TOTAL		5,215.96	1,779.20

Report Ref No. CS3/LPC22004291/Tvy3e2-1



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)

1,400.00

Report Ref No. CS3/LPC22004291/Tvy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

**Automotive Assessor** 

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.