



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref: CS3/AIG21012694/Kqy3e2-1

78 SHENTON WAY #09-16

Date: 30/06/2022

AIG BUILDING

SINGAPORE 079120

ATTN: IVAN TAM

Code: AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKA 9800M	<b>Veh. Inspected</b>	SMH 1676Y
<b>Policy No.</b>	7210032440	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	3885587035SG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVAN TAM	<b>Assign Date</b>	28/06/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA 3 (A)	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	JM6BN24A8K0258679	<b>Colour</b>	METALLIC GREY
<b>Odometer</b>	40035 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/60 R16	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	205/60 R16	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	205/60 R16	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	205/60 R16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	10/12/2021	<b>Inspection Date</b>	15/12/2021
<b>Survey held at</b>	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		

### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>4 Working Days</b>
--	-----------------------