



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SMH1676Y

Report No. : PAS/TP/0131221

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	1 pc	Frt door RH	Dented/Distorted	\$ 1,200.40	\$ 1,200.40
2	1 pc	Frt door weatherstrip RH	Necessary	\$ 134.50	\$ 134.50
3	1 pc	Frt door inner trim board RH	Dented/Loop Cracked	\$ 763.40	\$ 763.40
4	1 pc	Frt door lock RH	Refit	\$ 251.10	\$ -
5	1 pc	Frt door regulator	Bent	\$ 182.40	\$ 182.40
6	1 pc	Rr door RH	Dented/Distorted	\$ 1,084.30	\$ 1,084.30
7	2 pcs	Rr door hinge top/bot RH	Dented/Bent	\$ 75.60	\$ 75.60
8	1 pc	Rr door checker RH	Serviceable	\$ 38.90	\$ -
9	1 pc	Rr door weatherstrip RH	Necessary	\$ 134.50	\$ 134.50
10	1 pc	Rr door inner trim board RH	Dented/Cracked	\$ 684.20	\$ 684.20
11	1 pc	Rr door lock RH	Serviceable	\$ 188.70	\$ -
12	1 pc	Rr door regulator	Refit	\$ 138.20	\$ -
13	1 pc	RH center door pillar	Dented/Repair		(Refer labour no. 4 & 5)
				\$ 4,876.20	\$ 4,259.30
Less Discount : 20%				\$ 975.24	\$ 851.86
List Parts Sub-Total :				\$ 3,900.96	\$ 3,407.44
Parts Total :				\$ 3,900.96	\$ 3,407.44





# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SMH1676Y

Report No. : PAS/TP/0131221

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove and reinstall affected electrical wiring system for necessary repairs. To check affected electrical wiring system.	\$ 30.00	\$ 20.00
2	To transfer RHF door component parts to new door.	\$ 100.00	\$ 80.00 60%
3	To transfer RHR door component parts to new door.	\$ 100.00	\$ 80.00 60%
4	To remove and reinstall RH center interior trims, garnishes, seats, etc. for necessary repairs. To straighten, repair, realign on affected area and replace damaged parts.	\$ 800.00	\$ 330.00
5	To spray painting, blending on affected and adjacent area.	\$ 800.00	\$ 550.00 44%
6	To spray anti-rust coating on new and affected panels.	\$ 60.00	\$ 60.00
Labour Total :		\$ 1,890.00	\$ 1,120.00
Total (Parts & Labour) :		\$ 5,790.96	\$ 4,527.44

## For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 3,620.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 4 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

33 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

4 days

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.