



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0131221

Date of Report : 08/01/2022

To : Ms Tan Mei Yan
C/o. 160 Sin Ming Drive
#05-08 Sin Ming Autocity
Singapore 575722

Date of Assignment : 14/12/2021
Report requested by : Ms Tan Mei Yan
Date of Accident : 10/12/2021
Date of Inspection : 14/12/2021
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SMH1676Y
Make & Model : Mazda 3 1.5 5drs
Date of Registration : 14/01/2019
Colour : Met. Grey

Engine Capacity (cc) : 1496cc
Mileage (km) : 40035km
Chassis / Frame No. : JM6BN24A8K0258679
Engine No. : P520559336

TYRE CONDITION

Front LH : 6 mm
Make : Bridgestone

Front RH : 6 mm
Make : Bridgestone

Rear LH : 6 mm
Make : Bridgestone

Rear RH : 6 mm
Make : Bridgestone

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Kum Chew Motor Workshop
160, Sin Ming Drive, #05-08, Sin Ming Autocity, Singapore 575722

ASSESSMENT

Repairer's Estimate : \$ 5,790.96
Revised Amount : \$ 4,527.44
Less Excess : \$ -
Recommended Reserve : \$ 3,620.00 (Lump Sum)

Estimated Normal Period of Repairs : 4 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addressees (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may be protected by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SMH1676Y

Report No. : PAS/TP/0131221

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Kum Chew Motor Workshop, 160, Sin Ming Drive, #05-08, Sin Ming Autocity, Singapore 575722.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the RHS portion.

DAMAGES

The RHF door, RHR door, RH center door pillar, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$4,527.44.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$3,620.00.

This inspection was conducted entirely on a '**Without Prejudice**' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SMH1676Y

Report No. : PAS/TP/0131221

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	1 pc	Frt door RH	Dented/Distorted	\$ 1,200.40	\$ 1,200.40
2	1 pc	Frt door weatherstrip RH	Necessary	\$ 134.50	\$ 134.50
3	1 pc	Frt door inner trim board RH	Dented/Loop Cracked	\$ 763.40	\$ 763.40
4	1 pc	Frt door lock RH	Refit	\$ 251.10	\$ -
5	1 pc	Frt door regulator	Bent	\$ 182.40	\$ 182.40
6	1 pc	Rr door RH	Dented/Distorted	\$ 1,084.30	\$ 1,084.30
7	2 pcs	Rr door hinge top/bot RH	Dented/Bent	\$ 75.60	\$ 75.60
8	1 pc	Rr door checker RH	Serviceable	\$ 38.90	\$ -
9	1 pc	Rr door weatherstrip RH	Necessary	\$ 134.50	\$ 134.50
10	1 pc	Rr door inner trim board RH	Dented/Cracked	\$ 684.20	\$ 684.20
11	1 pc	Rr door lock RH	Serviceable	\$ 188.70	\$ -
12	1 pc	Rr door regulator	Refit	\$ 138.20	\$ -
13	1 pc	RH center door pillar	Dented/Repair	(Refer labour no. 4 & 5)	
				\$ 4,876.20	\$ 4,259.30
Less Discount : 20%				\$ 975.24	20% \$ 851.86
List Parts Sub-Total :				\$ 3,900.96	\$ 3,407.44
Parts Total :				\$ 3,900.96	\$ 3,407.44



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SMH1676Y

Report No. : PAS/TP/0131221

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove and reinstall affected electrical wiring system for necessary repairs. To check affected electrical wiring system.	\$ 30.00	\$ 20.00
2	To transfer RHF door component parts to new door.	\$ 100.00	\$ 80.00
3	To transfer RHR door component parts to new door.	\$ 100.00	\$ 80.00
4	To remove and reinstall RH center interior trims, garnishes, seats, etc. for necessary repairs. To straighten, repair, realign on affected area and replace damaged parts.	\$ 800.00	\$ 330.00
5	To spray painting, blending on affected and adjacent area.	\$ 800.00	\$ 550.00
6	To spray anti-rust coating on new and affected panels.	\$ 60.00	\$ 60.00
Labour Total :		\$ 1,890.00	\$ 1,120.00
Total (Parts & Labour) :		\$ 5,790.96	\$ 4,527.44

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 3,620.00

Under normal circumstances, the repairs should be completed within a reasonable period

of **4 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

33 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

















