

# Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578  
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578  
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050  
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523  
( Email Address : woonmeng @singnet.com.sg )  
Co Reg No. 200603678M GST Reg No. 20-0603678M

## Estimate

## TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd  
Motor Claims Dept

Date : 24 Aug 2022

Dear Sirs :

Fax : 6224 1047

### RE : ESTIMATE COST FOR MAXUS G10 - GBL1789P ACCIDENT INVOLVING GBL1789P & GBF7739B ON 26/06/2022

| <u>ITEMS</u> | <u>DESCRIPTION</u>              | <u>QTY</u> | <u>PRICE</u>                 |
|--------------|---------------------------------|------------|------------------------------|
| 1            | Rear bumper                     | 1pc        | \$ 1,914.00 <i>del 1614</i>  |
| 2            | Rear bumper retainer @\$83.17ea | 2pcs       | \$ 166.34 <i>X n</i>         |
| 3            | Rear rubber                     | 1pc        | \$ 369.15 <i>X n</i>         |
| 4            | Rear bootlid                    | 1pc        | \$ 3,469.12 <i>ht 3069</i>   |
| 5            | Rear bootlid outer handle       | 1pc        | \$ 289.00 <i>X n</i>         |
| 6            | SAIC motor                      | 1pc        | \$ 159.00 <i>del</i>         |
| 7            | Maxus                           | 1pc        | \$ 165.11 <i>na</i>          |
| 8            | G10                             | 1pc        | \$ 125.30 <i>na</i>          |
| 9            | Emblem                          | 1pc        | \$ 188.00 <i>na</i>          |
| 10           | Rear sensor @195ea              | 2pcs       | \$ 390.00 <i>na 200 SN</i>   |
|              |                                 |            | \$ 7,235.02                  |
| 11           | 8pax                            | 1pc        | \$ 15.00 <i>del</i>          |
| 12           | 70km/h                          | 1pc        | \$ 15.00 <i>na</i>           |
| 13           | Rear windscreen sealant         | 2pcs       | \$ 40.00 <i>del</i>          |
|              | <b>Sum Carriage Forward</b>     |            | <b>\$ 7,305.02</b> <i>70</i> |

5320.41  
10% 4788.37  
SN 200

**Sum Carriage Forward**

**\$ 7,305.02**

**Labour Charge & Misc**

To remove, replace, repair & weld  
rear damaged parts.

}  
}

\$ 800.00 600

To R & R rear windscreen glass

\$ 150.00 120

To numbering company logo

\$ 350.00 200

To R & R sensor wiring.

\$ 100.00 30

To putty & spray painting

\$ 700.00 600

**Total**

**\$ 9,405.02 1550**

All prices quoted are subjected to 7% GST.

4788.37  
200  
70  
1550  
-----  
6608.37  
455250  
5 days #

This is a computer generated document. No signature is required.

consultants hence  
er of the following:  
survey before/after spray painting  
display damaged part(s) during resurvey  
parts prices are subject to confirmation  
third party survey is on a "Without Prejudice" basis  
illegal modification(s) is allowed  
complementary item(s) must be resurveyed and  
subject to final approval from Insurance Company

• acknowledged by Repairer

ature:

Tanpik 97445745  
-wp- 73/8/22  
45 resurvey after repair  
05 day