

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 24/06/2022
TP Veh Reg No: SNB578H

Estimate No: EST2200204
Date: 27 Jun 2022

Veh Reg No: SMN206X
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3601179931
Reg. Date: 23/07/2019
Your Ref No: SNB578H

Xiao Tony

Estimate Repair Cost to Vehicle No :SMN206X

Quantity	Description	List Price SS	Amount SS
List Price			
1	1 PC BOOT LID <i>Dented</i>	658.70 ✓	
2	2 PCS BOOT LID HINGE <i>new</i>	154.60 x	
3	1 PC BOOTLID LOGO <i>new</i>	52.20 ✓	
4	1 PC BOOT LID "VIOS" EMBLEM <i>new</i>	45.50 ✓	
5	1 PC BOOT LID "E" EMBLEM	42.20 ✓	
6	1 PC BOOT LID LAMP LH <i>new</i>	388.60 x	
7	1 PC BOOT LID LAMP RH <i>new</i>	388.60 x	
8	1 PC BOOT LID LOCK <i>Damaged</i>	360.40 -	
9	1 PC BOOT LID RUBBER <i>nt</i>	166.40 -	
10	1 PC BOOT LID TRIM <i>new</i>	208.50 x	
11	1 PC REAR PANEL <i>Dented</i>	620.10 ✓	
12	1 PC REAR PANEL TRIM <i>Dented</i>	232.20 ✓	
13	1 PC TAIL LAMP LH <i>crushed</i>	397.70 ✓	
14	1 PC TAIL LAMP - RH <i>new</i>	397.70 x	
15	1 PC REAR FENDER TRIM LH <i>Dented</i>	355.90 x	245
16	1 PC REAR BUMPER <i>Dented</i>	482.60 -	
17	1 PC REAR BUMPER REINFORCEMENT <i>Dented</i>	316.60 -	
18	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	227.80 -	
19	2 PCS REAR BUMPER SMALL RETAINER <i>new LH and</i>	181.20 x	90.60
20	1 PC REAR BUMPER REFLECTOR - RH <i>crushed</i>	98.70 -	
21	1 PC REAR BUMPER REFLECTOR - LH	98.70 -	
22	1 PC REAR BUMPER MUDFLAP LH <i>new</i>	56.90 x	
<i>Rear Antenna Sensor 169.50 Shorted</i>		5.931.80	
Less 25%		1.482.95	4.448.90
Special Net			
23	1 SET BOOTLID TRIM CLIPS <i>new</i>	60.00 x	
24	1 PC BOOT LID NUMBER '624' STICKER <i>new</i>	45.00 -	
25	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00 x	20

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 24/06/2022
TP Veh Reg No: SNB578H

Estimate No: EST2200204
Date: 27 Jun 2022

Veh Reg No: SMN206X
Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3601179931
Reg. Date: 23/07/2019
Your Ref No: SNB578H

Estimate Repair Cost to Vehicle No :SMN206X

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
26	1 SET REAR FENDER TRIM CLIPS LH <i>new</i>	60.00 30	
27	1 PC REAR FENDER STICKER LH <i>new</i>	290.00 250	
28	1 SET REAR BUMPER CLIPS <i>new</i>	40.00 30	
29	2 PCS "L" PLATE BRACKET <i>new</i>	100.00 50	
30	1 SET REAR BUMPER STICKER <i>new</i>	280.00 250	
31	1 SET REAR BUMPER MUDFLAP CLIPS LH <i>new</i>	30.00 X	
32	1 PC REAR NUMBER PLATE <i>new</i>	50.00 X	
		995.00	995.00
	Labour		
33	1 TO CHECK WIRING	50.00 30	
34	1 TO REPLACE STICKERS	80.00 50	
35	1 TO SPRAY UNDERSEAL	100.00 60	
36	1 (REAR) TO SPRAY PAINTING	1,200.00 900	
37	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 800	
		2,630.00	2,630.00

To remove upholstery. *150 80*

To transfer boothie fittings. *150 60*

Adrian Lij
4/8 27/06/22
06 Dugji

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 24/06/2022
TP Veh Reg No: SNB578H

Estimate No: EST2200204
Date: 27 Jun 2022

Veh Reg No: SMN206X
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3601179931
Reg. Date: 23/07/2019
Your Ref No: SNB578H

Estimate Repair Cost to Vehicle No :SMN206X

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	Total		S\$ 8,073.90
	Add GST @ 7%		565.17
	Total Amount Payable		<u>S\$ 8,639.07</u>

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND SIX HUNDRED THIRTY NINE AND CENTS SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/s 27/06/22.
06 hrs.

Total: 5883.97

L/s: A7K.

4.7K.