

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

**M/S :** CHINA TAIPING INSURANCE (SINGAPORE) PTE  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

TEL: 63896111 FAX: 62247175  
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party  
Accident Date: 24/06/2022  
TP Veh Reg No: SNB578H

**Estimate No: EST2200204**

Date: 27 Jun 2022

Veh Reg No: **SMN206X**

Make/Model: TOYOTA VIOS 1.5E  
AUTO

Chasis No: MR2B23F3601179931

Reg. Date: 23/07/2019

Your Ref No: SNB578H

## Estimate Repair Cost to Vehicle No :SMN206X

| Quantity | Description                        | List Price | Amount     |
|----------|------------------------------------|------------|------------|
|          |                                    | <u>S\$</u> | <u>S\$</u> |
|          | <b>List Price</b>                  |            |            |
| 1        | 1 PC BOOT LID                      | 658.70     |            |
| 2        | 2 PCS BOOT LID HINGE               | 154.60     |            |
| 3        | 1 PC BOOTLID LOGO                  | 52.20      |            |
| 4        | 1 PC BOOT LID "VIOS" EMBLEM        | 45.50      |            |
| 5        | 1 PC BOOT LID "E" EMBLEM           | 42.20      |            |
| 6        | 1 PC BOOT LID LAMP LH              | 388.60     |            |
| 7        | 1 PC BOOT LID LAMP RH              | 388.60     |            |
| 8        | 1 PC BOOT LID LOCK                 | 360.40     |            |
| 9        | 1 PC BOOT LID RUBBER               | 166.40     |            |
| 10       | 1 PC BOOT LID TRIM                 | 208.50     |            |
| 11       | 1 PC REAR PANEL                    | 620.10     |            |
| 12       | 1 PC REAR PANEL TRIM               | 232.20     |            |
| 13       | 1 PC TAIL LAMP LH                  | 397.70     |            |
| 14       | 1 PC TAIL LAMP - RH                | 397.70     |            |
| 15       | 1 PC REAR FENDER TRIM LH           | 355.90     |            |
| 16       | 1 PC REAR BUMPER                   | 482.60     |            |
| 17       | 1 PC REAR BUMPER REINFORCEMENT     | 316.60     |            |
| 18       | 2 PCS REAR BUMPER SIDE RETAINER    | 227.80     |            |
| 19       | 2 PCS REAR BUMPER SMALL RETAINER   | 181.20     |            |
| 20       | 1 PC REAR BUMPER REFLECTOR - RH    | 98.70      |            |
| 21       | 1 PC REAR BUMPER REFLECTOR - LH    | 98.70      |            |
| 22       | 1 PC REAR BUMPER MUDFLAP LH        | 56.90      |            |
|          |                                    | 5,931.80   |            |
|          | Less 25%                           | 1,482.95   | 4,448.90   |
|          | <b>Special Net</b>                 |            |            |
| 23       | 1 SET BOOTLID TRIM CLIPS           | 60.00      |            |
| 24       | 1 PC BOOT LID NUMBER '624' STICKER | 45.00      |            |
| 25       | 1 SET REAR PANEL TRIM CLIPS        | 40.00      |            |

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

**M/S :** CHINA TAIPING INSURANCE (SINGAPORE) PTE  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

TEL: 63896111 FAX: 62247175  
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party  
Accident Date: 24/06/2022  
TP Veh Reg No: SNB578H

**Estimate No:** EST2200204  
**Date:** 27 Jun 2022

**Veh Reg No:** SMN206X  
**Make/Model:** TOYOTA VIOS 1.5E  
AUTO

**Chasis No:** MR2B23F3601179931  
**Reg. Date:** 23/07/2019  
**Your Ref No:** SNB578H

## Estimate Repair Cost to Vehicle No :SMN206X

| Quantity | Description                                                                                                         | List Price | Amount     |
|----------|---------------------------------------------------------------------------------------------------------------------|------------|------------|
|          |                                                                                                                     | <u>S\$</u> | <u>S\$</u> |
| 26       | 1 SET REAR FENDER TRIM CLIPS LH                                                                                     | 60.00      |            |
| 27       | 1 PC REAR FENDER STICKER LH                                                                                         | 290.00     |            |
| 28       | 1 SET REAR BUMPER CLIPS                                                                                             | 40.00      |            |
| 29       | 2 PCS "L" PLATE BRACKET                                                                                             | 100.00     |            |
| 30       | 1 SET REAR BUMPER STICKER                                                                                           | 280.00     |            |
| 31       | 1 SET REAR BUMPER MUDFLAP CLIPS LH                                                                                  | 30.00      |            |
| 32       | 1 PC REAR NUMBER PLATE                                                                                              | 50.00      |            |
|          |                                                                                                                     | 995.00     | 995.00     |
|          | <b>Labour</b>                                                                                                       |            |            |
| 33       | 1 TO CHECK WIRING                                                                                                   | 50.00      |            |
| 34       | 1 TO REPLACE STICKERS                                                                                               | 80.00      |            |
| 35       | 1 TO SPRAY UNDERSEAL                                                                                                | 100.00     |            |
| 36       | 1 (REAR) TO SPRAY PAINTING                                                                                          | 1,200.00   |            |
| 37       | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS,<br>KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR<br>CUTTING/WELDING WORKS. | 1,200.00   |            |
|          |                                                                                                                     | 2.630.00   | 2.630.00   |

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

**M/S :** CHINA TAIPING INSURANCE (SINGAPORE) PTE  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

TEL: 63896111 FAX: 62247175  
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party  
Accident Date: 24/06/2022  
TP Veh Reg No: SNB578H

**Estimate No:** EST2200204  
**Date:** 27 Jun 2022

**Veh Reg No:** SMN206X  
**Make/Model:** TOYOTA VIOS 1.5E  
AUTO  
**Chasis No:** MR2B23F3601179931  
**Reg. Date:** 23/07/2019  
**Your Ref No:** SNB578H

## Estimate Repair Cost to Vehicle No :SMN206X

| Quantity | Description          | List Price | Amount       |
|----------|----------------------|------------|--------------|
|          |                      | S\$        | S\$          |
|          | Total                |            | S\$ 8,073.90 |
|          | Add GST @ 7%         |            | 565.17       |
|          | Total Amount Payable |            | S\$ 8,639.07 |

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND SIX HUNDRED THIRTY NINE AND CENTS  
SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time  
which may be required after work has begun.

**For Kang Car Repairers Pte Ltd**



AUTHORISED SIGNATURE