

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation	Internationale Des Experts En Autor	nobile CS3/	A SM22002008
AXA INSURANCI		Ref:		2002030/Eqy3
8 SHENTON WAY #24-01		Date		<b>-</b> 08/06/2022
AXA TOWERSIN				
		Code	e: ASM	
	Policy Part	ticulars :- (THIRD PARTY CLA	IM)	
Insured Veh.	SHC 5684H	Veh. Inspected	SJA 5751J	
Policy No.		Coverage (\$)	0.00	
Claim No.	S2M03UZ7	Excess (\$)	0.00	
Assign From	LOH Cynthia	Assign Date	07/03/2022	<b>-</b> 08/06/2022
<u> </u>	Vehic	cle Particulars & Condition		
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3.		Conditions of Tyres		
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
l.	D	Description of Damages		
<u> </u>		General Information		
Accident Date	04/03/2022	Inspection Date	07/03/2022	
Survey held at	MASTER CAR SPRAY SERVICE			
	36 TOH GUAN ROAD EAST #01-48 ENTERPRISE HUB			
·_	SINGAPORE 608580	Damanla		
Sa.	TON WAS CONDUCTED	Remarks	A C.I.C.	
B) THE REPAIR I	ESTIMATE WAS NOT PR	ON A "WITHOUT PREJUDICE" BARESENTED AT THE TIME OF INSE		
	WAS TOLD TO PREPARI LEASE FIND DAMAGED	VEHICLE PHOTOGRAPHS.		