



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No 57556
Reg No/Reg Date SLK8192B / 31/10/2016
Date In/Mileage / 65846
Chassis No WDD2221622A259185
Engine No 27682430374340
Make/Model MB/MB S 320 L SEDAN (V222)
Colour/Trim 024 474 Peridote Br/ 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
W1000558	Credit	28/06/2022/ 12:56	CH	371 / Go Chee Han					
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE : MSIG // 15-6-2022									
DRIVE IN/TP VEH NUMBER : 15-6-2022 // SMP825Z - TOKIO MARINE									
DATE IN/DATE SURVEY:									
DIRECT SETTLEMENT BY:									
A BPILAB									
STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT 960x2									
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH									
A BPIRES									
RESPRAY REAR BUMPER & TRUNK LID & END PANEL									
A BPILAB									
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT									
A BPILAB									
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT									
A BPILAB									
PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT (phsh)									
A BPILAB									
REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR. NETT (phsh)									
A BPILAB									
TO REMOVE & REPLACE REAR EXHAUST SYSTEM. NETT									
A BPILAB									
REMOVE CARRIAGE ASSY FROM FRAME, IMPACT. REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE. (phsh) 1920									
A BPILAB									
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT (phsh)									
A BPILAB									
REPLACE TRUNK LID TRANSFER WITH COMPONENT PARTS									
A 97250001									
CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM									

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han

DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 57556
Reg No/Reg Date SLK8192B / 31/10/2016
Date In/Mileage / 65846
Chassis No WDD2221622A259185
Engine No 27682430374340
Make/Model MB/MB S 320 L SEDAN (V222)
Colour/Trim 024 474 Peridote Br/ 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator	
WI000558	Credit	28/06/2022/ 12:56	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
A 97510101					120.00
BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS					25.00
M BPNSUN					
SUNDRY					
R	REAR BUMPER	1.00	2271.23	00.00	2271.23
R	REAR BUMPER LOWER PART TRIM	1.00	518.33	00.00	518.33
R	LH/REAR BUMPER CHROME TRIM	1.00	137.59	00.00	137.59
R	RH/REAR BUMPER CHROME TRIM	1.00	137.59	00.00	137.59
M	CTR/BASIC MOUNTING FOR BUMPER	1.00	155.06	00.00	155.06
M	LH/REAR BUMPER MOUNTING RAIL	1.00	102.22	00.00	102.22
M	RH/REAR BUMPER MOUNTING RAIL	1.00	102.60	00.00	102.60
M	LH/REAR TOP MOUNTING RAIL	1.00	27.02	00.00	27.02
M	RH/REAR TOP MOUNTING RAIL	1.00	27.02	00.00	27.02
M	LEFT REAR REFLECTOR	1.00	30.35	00.00	30.35
R	RIGHT REAR REFLECTOR	1.00	30.35	00.00	30.35
R	FOG TAIL LAMP	1.00	291.99	00.00	291.99
M	DISTANCE SENSOR	2.00	195.43	00.00	390.86
R	SPACER RING	6.00	7.10	00.00	42.60
M	ELECTRICAL WIRING HARNESS	1.00	565.04	00.00	565.04
M	LH/TAIL PIPE BRACKET	1.00	85.98	00.00	85.98
R	RH/TAIL PIPE BRACKET	1.00	85.98	00.00	85.98
M	LH/TAIL PIPE CHROME COVER	1.00	840.67	00.00	840.67
R	RH/TAIL PIPE CHROME COVER	1.00	840.67	00.00	840.67
R	REAR SWITCHING MODULE BRACKET	1.00	31.13	00.00	31.13
R	TRUNK LID	1.00	3137.98	00.00	3137.98
R	GROMMET	3.00	2.70	00.00	8.10
R	MERCEDES STAR	1.00	50.95	00.00	50.95
R	NUT	4.00	6.47	00.00	25.88
R	S-320 MODEL PLATE	1.00	136.59	00.00	136.59
R	END PANEL LINING LOADING SILL	1.00	272.20	00.00	272.20
R	RH/REAR TRIM PANEL LOADING SPACE	1.00	49.23	00.00	49.23
R	REAR CROSS MEMBER	1.00	1352.69	00.00	1352.69
R	REAR END PANEL	1.00	852.23	00.00	852.23

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No **57556**
Reg No/Reg Date **SLK8192B / 31/10/2016**
Date In/Mileage **/ 65846**
Chassis No **WDD2221622A259185**
Engine No **27682430374340**
Make/Model **MB/MB S 320 L SEDAN (V222)**
Colour/Trim **024 474 Peridote Br/ 048 805 Orient Beig**

Account No	Terms	Date/Time Printed	CSE	Operator				
WI000558	Credit	28/06/2022/ 12:56	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RH/REAR EXHAUST GAS LINE				1.00	3136.84	00.00	3136.84
M	RIGHT REAR LAMP COMBINATION				1.00	1111.08	00.00	1111.08
M	RH/REAR OUTER SHIELDING				1.00	83.44	00.00	83.44
M	RH/REAR INNER SHIELDING				1.00	83.53	00.00	83.53
M	WHITE SEAM SEALING COMPOUND				2.00	116.07	00.00	232.14
M	TS TWO-COMPONENT ADHESIVE				1.00	858.76	00.00	858.76
M	CAVITY PRESERVATIVE				1.00	116.04	00.00	116.04
M	ZINC DUST PAINT				1.00	66.41	00.00	66.41

ESTIMATE

Stev (LKK)
29/6/22, 12:17p

DD-M NL
Excess-?
10 yr
P/P
by BLG

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

LKK Auto Consultants hereby notify
the Repairer of the following:

• To resurvey the repairer's estimate

Authorized signatory and company stamp

• To resurvey the repairer's estimate

Nett **33,233.37**
7% GST on **33233.37** **2326.34**

Total Payable **35,559.71**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer

Signature:

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg