

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 06 Sep 2022

Preliminary Advice

Vehicle No	: SLK8192B	Accident Date	: 15/06/2022
Make	: MERCEDES-BENZ S320L	Policy No.	: 30002008064
Assignment Date	: 29/06/2022	Excess	: S\$1,000.00
Date of Inspection	: 29/06/2022	Est. Duration of Repair	: 15
Inspection At	: 29/06/2022		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,857.15 (Incl. supplementary \$623.78)
Revised Amount	:S\$	30,234.81
Check Items (Estimated)	:S\$	0.00
Total	:S\$	30,234.81 (Incl. supplementary \$623.78)

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	186,000.00
COE / PARF Rebate	:S\$	118,232.00
Salvage Value	:S\$	
Margin for Repair	:S\$	67,768.00

Remarks

- (X) The vehicle is economical for repair
- () The vehicle is not economical for repair
- (X) Part-by-Part repair
- () Lump Sum repair

- (X) Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.