



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 57556
Reg No/Reg Date SLK8192B / 31/10/2016
Date In/Mileage / 65846
Chassis No WDD2221622A259185
Engine No 27682430374340
Make/Model MB/MB S 320 L SEDAN (V222)
Colour/Trim 024 474 Peridote Br/ 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator				
W1000558	Credit	28/06/2022/ 12:56	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : MSIG // 15-6-2022								
DRIVE IN/TP VEH NUMBER : 15-6-2022 // SMP825Z - TOKIO MARINE								
DATE IN/DATE SURVEY:								
DIRECT SETTLEMENT BY:								
A BPILAB								
STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES								
RESPRAY REAR BUMPER & TRUNK LID & END PANEL								
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD. NETT								
A BPILAB								
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT								
A BPILAB								
PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT								
A BPILAB								
REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-								
CARPET FOR NECESSARY REPAIR. NETT								
A BPILAB								
TO REMOVE & REPLACE REAR EXHAUST SYSTEM. NETT								
A BPILAB								
REMOVE CARRIAGE ASSY FROM FRAME, IMPACT. REPLACE AND ASSEMBLE								
WHEEL BASE & ADJUST TO VEHICLE.								
A BPILAB								
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT								
A BPILAB								
REPLACE TRUNK LID TRANSFER WITH COMPONENT PARTS								
A 97250001								
CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM								

Confirmed & accepted by

Store (CLKK)
5/7/22

Authorized signatory and company stamp

Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehan.go@cyclocarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128178



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
86431303

Vehicle & Document Information

WIP No 57556
Reg No/Reg Date SLK8192B / 31/10/2016
Date In/Mileage / 65846
Chassis No WDD2221622A259185
Engine No 27682430374340
Make/Model MB/MB S 320 L SEDAN (V222)
Colour/Trim 024 474 Peridote Br/ 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator				
NI000558	Credit	29/06/2022/ 12:56	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A 97510101								120.00
BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS								25.00
M BPNSUN								
SUNDRY								
R	REAR BUMPER	1.00	2271.23	00.00				2271.23
R	REAR BUMPER LOWER PART TRIM	1.00	518.33	00.00				518.33
R	LH/REAR BUMPER CHROME TRIM	1.00	137.59	00.00				137.59
R	RH/REAR BUMPER CHROME TRIM	1.00	137.59	00.00				137.59
M	CTR/BASIC MOUNTING FOR BUMPER	1.00	155.06	00.00				155.06
M	LH/REAR BUMPER MOUNTING RAIL	1.00	102.22	00.00				102.22
M	RH/REAR BUMPER MOUNTING RAIL	1.00	102.60	00.00				102.60
M	LH/REAR TOP MOUNTING RAIL	1.00	27.02	00.00				27.02
M	RH/REAR TOP MOUNTING RAIL	1.00	27.02	00.00				27.02
M	LEFT REAR REFLECTOR	1.00	30.35	00.00				30.35
R	RIGHT REAR REFLECTOR	1.00	30.35	00.00				30.35
R	FOG TAIL LAMP	1.00	291.99	00.00				291.99
M	DISTANCE SENSOR	2.00	195.43	00.00				390.86
R	SPACER RING	6.00	7.10	00.00				42.60
M	ELECTRICAL WIRING HARNESS	1.00	565.04	00.00				565.04
M	LH/TAIL PIPE BRACKET	1.00	85.98	00.00				85.98
R	RH/TAIL PIPE BRACKET	1.00	85.98	00.00				85.98
M	LH/TAIL PIPE CHROME COVER	1.00	840.67	00.00				840.67
R	RH/TAIL PIPE CHROME COVER	1.00	840.67	00.00				840.67
R	REAR SWITCHING MODULE BRACKET	1.00	31.13	00.00				31.13
R	TRUNK LID	1.00	3137.98	00.00				3137.98
R	GROMMET	3.00	2.70	00.00				8.10
R	MERCEDES STAR	1.00	50.95	00.00				50.95
R	NUT	4.00	6.47	00.00				25.88
R	S-320 MODEL PLATE	1.00	136.59	00.00				136.59
R	END PANEL LINING LOADING SILL	1.00	272.20	00.00				272.20
R	RH/REAR TRIM PANEL LOADING SPACE	1.00	49.23	00.00				49.23
R	REAR CROSS MEMBER	1.00	1352.69	00.00				1352.69
R	REAR END PANEL	1.00	852.23	00.00				852.23

Confirmed & accepted by

Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehon.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No 57556
Reg No/Reg Date SLK8192B / 31/10/2016
Date In/Mileage / 65846
Chassis No WDD2221622A259185
Engine No 27682430374340
Make/Model MB/MB S 320 L SEDAN (V222)
Colour/Trim 024 474 Peridote Br/ 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator
W1000558	Credit	28/06/2022/ 12:56	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/REAR EXHAUST GAS LINE	1.00	3136.84	00.00	3136.84
M RIGHT REAR LAMP COMBINATION	1.00	1111.08	00.00	1111.08
M RH/REAR OUTER SHIELDING	1.00	83.44	00.00	83.44
M RH/REAR INNER SHIELDING	1.00	83.53	00.00	83.53
M WHITE SEAM SEALING COMPOUND	2.00	116.07	00.00	232.14
M TS TWO-COMPONENT ADHESIVE	1.00	858.76	00.00	858.76
M CAVITY PRESERVATIVE	1.00	116.04	00.00	116.04
M ZINC DUST PAINT	1.00	66.41	00.00	66.41

Star (CLK)

& 29/6/22, 12:00pm

00-M M

Excess?

15 to 45
P/P

by BL G

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

Nett 33,233.37
7% GST on 33233.37 2326.34

Total Payable 35,559.71

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop