- CS/MSG22006193/ECY3 ASS. RECOBY: Steve ASSIGNMENT SLK 8192B Yr Regn: 3/10/16 From: Veh No: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: ' (OD) TP | WS | TP RES | OD RES | EVA | INV | MV Truck / Trailer or Make: Mes (eles-Renz To Inspect Vehicle No: Insured / Std / NI / NA at Workshop m/s T/Radio: Insured | Std | NI | NA Sb.Reading Eng/No: Insured: C/No: Policy No. Gen. Cond: Good (Fa)r / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Excess: Sum Insured: Brake: Ingrder Jammed / Leaked / Burnt or (Client's Record) Modi: NII I SURIM I STD AVRIM OF Make of Veh; Tyre Size: (Policy Condition) BS / DUN / EXNOVA / GY) FS / LIZA / MIC / OHTSU / PIR / SUM! / N/S OIS Remark: The veh had commenced its TOYO / YOKO or . repair at the time of inspection. Rear Front Bal. or Market Value: R/Bal. R/Bal. Consistent?: Yes or No IDAC Accident Roort: UBal. L/Bal. Consistent?: Yes or No GIA / PR Seen: D.O.I. () D.O.A. Res.: Yes or No days Est Repairs: Survey held at 3 Val.: Yes or No Des. of Damages : Frt / Real / O/S / N/S / U/C / Rooftop or Lum Sum: CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Action / Instruction Date / Time Days Of Repair: Date/Time, File Pass to? : Prell. Report Survey Fee: Resurvey No. of Trip: : Final Report Transportation: Date/Time, File Return to? : Site Insp (\$ Add Fee: Photos : Interview (\$ Others : Tech. Invs (\$ Report Former: :Weellend (\$ Lump Sum / LB.J: 15 TOTAL



Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT 16 RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581 66431303

Vehicle & Document Information

WIP No 57556

Reg No/Reg Date

SLK8192B / 31/10/2016

Date In/Mileage

Chassis No

/ 65846 WDD2221622A259185

27682430374340

Engine No Make/Model

MB/MB S 320 L SEDAN (V222)

Colour/Trim

024 474 Peridote Br/ 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator					
W1000558	Credit	28/06/2022/ 12:56	СН	371 / Go Chee Han					
Links		Description of Good	s / Services		Qty	Unit Price	Disc%	A	mount
Z REQUEST Customer M BPNSUN	Request			FFICIAL	TA	XII	VV	01	CE
DRIVE IN	/TP VEH NU	: MSIG // 15-6-2022 IMBER : 15-6-2022 //	SMP825Z - T	OKIO MARINE		1			
DIRECT S	DATE SURVE	BY:		960×2	7/5	2		1920	5760.00
STRAIGHT DISASSEM A BPIRES	EN, REMOVE IBLE AND RE	SUPPORT ASSY FROM F PLACE ATTACHED DAMAG	RAME IMPACT ED PARTS &	r \	1 17			2400	2700.00
RESPRAY A BPILAB		R & TRUNK LID & END	1					290	480.00
IDENTIF	NTRY DIAGN	OSTIC TO CHECK ON CO	NTROL UNIT	RESET MEMORY TO					120.00
	AR LIGHTIN	IG SYSTEM AND WATER T	EST FOR ANY	LEAKAGE. NETT			0.07	1	1000.00
A BPILAB PLACE VE A BPILAB	HICLE ON-T	O CELLETTE BENCH & C	ONDUCT CHAS		hop)		0,0,		960.00
REMOVE 8		GAGE COMPARTMENT,TRI	M, GARNISH-	Cph+)					
	E & REPLAC	CE REAR EXHAUST SYSTE	M.NETT					1	420.00
		SSY FROM FRAME, IMPAC	T.REPLACE A	ND ASSEMBLE (phoh) 1	920			,	2160.00
A BPILAB		JCT WHEEL ALIGNMENT.N	етт Д	Y				7	540.00
A BPILAB		TRANSFER WITH COMPON	- 1						480.00
A 97250001 CAVITY F	RESERVATIO	ON ON REPLACED OR REP	AIRED BODY	PANELS PERFORM					180.00

Confirmed & accepted by

Go Chee Han

DID: 6771 4336 HP: 9181 7717 Email: cheehan.go@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Eustomer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 1 of 3





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT 16 RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581 66431303

Vehicle & Document Information

WIP No 57556

Reg No/Reg Date

SLK8192B / 31/10/2016

Date In/Mileage

/ 65846 Chassis No WDD2221622A259185

Engine No

27682430374340

Make/Model

MB/MB S 320 L SEDAN (V222)

Colour/Trim

024 474 Peridote Br/ 048 805 Orient Beig

Account No	Terms	Date/Time Prin	ted	CSE	Oper	rator		1				
11000558	Credit	28/06/2022/	12:56	СН	371	/ Go	Chee Han					
		Description	of Good	s / Services				Qty	U	nit Price	Disc%	Amount
BEADS, SE BEADS, SE BENSUN SUNDRY		LANGES ON REP	LACEMENT	BODY PAN	ELS/ COMF	PONENT	3 AL	. T	4)		VV	O C25.0
R REAR BUMP	PER /	< OD						1.00	_ 2	271.23	00.00	2271.2
		PART TRIM /	WIZ					1.00		518.33		518.3
	SUMPER CHR		N					1.00	-	137.59	00.00	137.5
	SUMPER CHR		ne					1.00		137.59	00.00	137.5
CTR/BASIC	MOUNTING	FOR BUMPER	ļ				0	1.00	1	155.06	00.00	155.0
LH/REAR E	SUMPER MOU	NTING RAIL				1	111	1 00		102.22		102.2
RH/REAR E	SUMPER MOU	NTING RAIL 7			^	11	117/	1.00		102.60		102.6
LH/REAR T	OP MOUNTI	NG RAIL			111	IMI	120	1.00		27.02		27.0
RH/REAR T	OP MOUNTI	NG RAIL ".		1	1111	41/,	(L)	1.00		27.02		27.0
LEFT REAF	REFLECTO			11	1111	1	,	1.00		30.35		30.3
RIGHT REA	R REFLECT	OR / OP	12	1/	110	*		1.00		30.35		30.1
FOG TAIL	LAMP /	BR 3	(100			1.00		291.99		291.9
DISTANCE	SENSOR !	C. Carrier	-	7) 6				2.00		195.43		390.8
SPACER RI			٠ حـ	//				6.00		7.10		42.6 565.0
	L WIRING		1					1.00		565.04 85.98		85.9
	IPE BRACK		Market Land					1.00		85.98		85.9
	IPE BRACK							1.00		840.67		840.6
LH/TAIL F	IPE CHROM	E COVER	0					1.00		840.67		840.6
		E COVER / D	C BR					1.00		31.13		31.
		ULE BRACKET	/ UK					1.00	3	137.98	100	3137.9
TRUNK LIC								3.00	3	2.70		8.1
GROMMET	CTAD PK	ne						1.00		50.95	00.00	50.9
MERCEDES	SIAR	,						4.00		6.47	00.00	25.8
NUT		/ nc						1.00		136.59		136.5
S-320 MOD	LINING L		- QR					1.00		272.20		272.2
ENU PANEL	DIM DANEL	OADING SILL	/0	R				1.00	,	49.23		49.2
REAR CROS	KIM PANEL	LOADING SPACE	. , ,					1.00	1	352.69	00.00	1352.6
	3 MEMBER							1.00		352.23		852.2

Confirmed & accepted by

Go Chee Han DID: 6771 4336 HP: 9181 7717 Email: cheehan.go@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.


Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 2 of 3





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT 16 RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581 66431303

Vehicle & Document Information

57556

Reg No/Reg Date

WIP No

Chassis No

SLK8192B / 31/10/2016

Date In/Mileage 65846

WDD2221622A259185

27682430374340 **Engine No**

Make/Model

MB/MB S 320 L SEDAN (V222)

				Colour/Trim	024 474 Per	024 474 Peridote Br/ 048 805 Orient Beig			
Account No	Terms	Date/Time Printed	CSE	Operator					
11000558	Credit	28/06/2022/ 12	56 CH	371 / Go Che	ee Han				
		Description of	Goods / Service	es	Qty	Unit Price Disc%	Amount		
RIGHT REAR OF RH/REAR OF RH/REAR OF WHITE SEAR OF TS TWO-CO	OUTER SHIE INNER SHIE AM SEALING OMPONENT A RESERVATIV	MBINATION DI LDING 2 COMPOUND 2 DHESIVE	98 N	OFFICI	1.00 1.00 1.00 1.00 2.00 1.00 1.00	3136.84 00.00 1111.08 00.00 83.44 00.00 83.53 00.00 116.07 00.00 858.76 00.00 116.04 00.00 66.41 00.00	3136.6 1111.6 83.4 83.5 232. 858. 116.6 66.4		
			31	INAI					
	Steve	(LKK) 19/6/22, 12.1	n'	10 41					
	,	۱۰۰۰		pp of	DID: 6771 43 Email: cheehan.go	hee Han 36 HP: 9181 7717 @cyclecarriage.com.sg ge Industries Pte Ltd Centre - Pandan Lop			

Confirmed	&	acce	pted	by
Committee	•	avve		~,

LKK Auto Consultants here e notify the Repairer of the . To resurve in unting Authorized signatory and company stamp resurvey

33,233.37 7% GST on 33233.37 2326.34

> **Total Payable** 35,559.71

Validity of this estimate is 14 days from date of quests This Conguter generated document, no signature is required.

Estimated costs quoted are excluding 6ST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 500 of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windstreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring

the removal of the windscreen.
Acknowledged by Repairer Signature:

Date:

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg SC1S226F0002 / CYCLE & CARRIAGE INDUSTRIES PTE LTD ENTRY DATE & TIME: 15/06/2022 12:06 (SGT) SUBMITTED BY: Jasmine Chua VERSION: 1 (15/06/2022 12:06 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorised Driver
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation of witholding of material lacts may allow insurance companies.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

15/06/2022 12:06 (SGT) 15/06/2022 08:30 (SGT) Singapore

BEDOK SOUTH AVE 1

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLK8192B

Yes

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address**

1XXXXX367W CHEEWEI.TEO@CYCLECARRIAGE.COM.SG (Phone) +65-64733122 +65-64733122

Mercedes

S320

VEHICLE PARTICULARS

Alternative Phone No

Mobile Phone No

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission CC

No - Claiming third party

Private car Auto 2998

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy **Policy Number** Cover Note Number

MSIG Insurance (Singapore) Pte. Ltd. Comprehensive

CYCLE & CARRIAGE INDUSTRIES PTE LTD

No

DRIVER

Name of Driver NRIC No

LAU AH BEE SXXXX962F

Accident report SC1S226F0002

Page 1 of 18



Date Of Birth 21/09/1955 Occupation Indoor Date Of Driving Pass 02/02/1993 Driving experience 29 YEARS AND 4 MONTHS Gender Mobile Number (Phone) +65-94499676 Alt. Phone Number **Email Address** NO@EMAIL.COM Address 333 ONAN ROAD Address complement Postcode

424724 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured LOAN CAR Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear Weather Conditions Raining Road Surface Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING AT THE RIGHT MOST LANE, SUDDENLY CAR 'B' KNOCKED INTO MY CAR REAR PORTION.

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMP825Z Vehicle Manufacturer Toyota Vehicle Model Vehicle Variant Vehicle Colour Black Vehicle Category Private car Name of Driver Passport No/FIN

SOH CHENG YEE JEREMY SXXXX334C

Contact Number (Phone) +65-97975568 Address

Accident report SC1S226F0002

Page 2 of 18



SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

PAULAN Signature Policyholder

BELT LARE

& keineR

Date & Time

Driver's Signature


(If driver is not the policyholder)

Go Chee Han DID: 6771 4336 HP: 9181 7717 Email: cheehan.go@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop
Reporting Centre Personnel's
Name:

Cycle & Carriage Industries Pte Ltd

Version 1.3 | Updated 02 DEC 2020





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling at oright most lane, Suddenly Car 'B" Knocked into my car new portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

eu.

Policyholder s Signature
Date & Time

Driver's Signature (If driver is not the policyholder) Date & Time Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehan.go@cyclecarriage.com.s
Cycle & Carriage Industries Pte Ltd
Cycle & Carriage Industries Pte Ltd
Cycle & Carriage Industries Pandon Los

Name:

Cycle & Carriage Industries Pte Ltd

Version 1.3 | Updated 02 DEC 2020

