



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLK8192B

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No 57556
Reg No/Reg Date SLK8192B / 31/10/2016
Date In/Mileage 04/07/2022/ 65846
Chassis No WDD2221622A259185
Engine No 27682430374340
Make/Model MB/MB S 320 L SEDAN (V222)
Colour/Trim 024 474 Peridote Br/ 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator	
WI000558	Credit	26/08/2022/ 18:57	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPN SUN

POLICY NO/ACC DATE : MSIG // 15-6-2022

DRIVE IN/EXCESS : 15-6-2022 // \$1000

DATE IN/DATE SURVEY: 29-6-2022 // STEVE - LKK

DIRECT SETTLEMENT BY: 30-6-2022 // CELINE - LKK

X BLIND RIVET	30.00	1.70	00.00	NEC	51.00 ✓
X PAN HEAD RIVET WITH BORE	3.00	7.10	00.00	NEC	21.30 ✓
X RIVET	40.00	2.73	00.00	NEC	109.20 ✓
X REAR SWITCHING MODULE	1.00	154.53	00.00	CRU	154.53 ✓
X NUT	4.00	6.47	00.00	NEC	25.88 ✓
X TRUNK LID MOULDING	1.00	215.50	00.00	CRU	215.50 ✓
X SURFACE GASKET	1.00	19.67	00.00	NEC	19.67 ✓
X EXPANSION RIVET	10.00	2.67	00.00	NEC	26.70 ✓

ESTIMATE

Confirmed & accepted by

7% GST on **Nett 623.78** **43.66**

Authorized signatory and company stamp

Total Payable 667.44

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg