

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGV858SC

at Workshop m/s

imperium

of

Insured:

SKX7075X

Policy No.

Claims No.

SNM720204521/02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$77k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

882.1

Vehicle: IN / OUT

Date:

Person Contacted:

L7A845088

Veh No:

SGV858SC

Yr Regn:

14/09/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer of

A/ Avantgarde

Make:

Mer Benz C180

c.c

1595

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

103812

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD2050402R089364

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

27/06/22

D.O.I.

29/06/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Ltr O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 19k.

have video of Bldg

SGV858SC 4891D

18/7/22 4/5 @ 9000 in bond shown. (Red @ 10950.79, 55%)

Date/Time, File Pass to?

☐

Preli. Report

1)

20/7/22

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

MER-TP

Lump Sum / LB.I: (\$

9000

TOTAL

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

28 Jun 2022

Vehicle No.: SGV 8585 C

Model: Mercedes Benz C180

*Not Authorized
29/06/22
2/5 \$ 9000/
4 days*

QTY	DESCRIPTION	AMT S\$
	<u>List Items</u>	
1	Front bonnet <i>Sent / Rec 2215</i>	\$ 2,883.00 ✓
1	Front bonnet lock catch -RH <i>11</i>	\$ 145.00 X
1	Front bonnet lock -RH <i>twi 225-30</i>	\$ 265.00 ✓
1	Front bonnet logo <i>Rec</i>	\$ 68.00 ✓
1	Front bonnet centre safety lock <i>11</i>	\$ 135.00 X
1	Front headlamp -RH <i>CNE</i>	\$ 3,617.00 ✓
1	Front bumper inner top retainers <i>CNE</i>	\$ 218.00 ✓
1	Front bumper <i>Dis 1636.54</i>	\$ 1,887.00 ✓
1	Front bumper inner frame <i>Dis</i>	\$ 199.00 ✓
1	Front bumper clip (1 set) <i>Rec</i>	\$ 65.00 ✓
1	Front bumper under cover <i>CNE 242.50</i>	\$ 250.00 ✓
1	Front bumper side grille <i>Dis twi/cut</i>	\$ 142.00 ✓
1	Front bumper lower grille <i>twi</i>	\$ 182.00 ✓
1	Front bumper reinforcement <i>Sent</i>	\$ 522.00 ✓
1	Front bumper side retainers <i>Dis CNE 115.32</i>	\$ 151.00 ✓
1	Front bumper tow hook cover <i>CNE bumper</i>	\$ 50.00 X
4	Front bumper PDC sensors <i>should 182.70 x 2 = 365.40</i>	\$ 1,432.00 2PCS ✓
1	Front bumper sponge <i>Torn</i>	\$ 185.00 ✓
1	Front fender -RH <i>R</i>	\$ 1,085.00 X
1	Front support panel <i>R</i>	\$ 958.00 X
1	Front bumper PDC sensor control unit <i>CNE 818</i>	\$ 14,439.00
1	Front fender inner shield <i>Dis Torn 827.32</i>	Less 10% \$ 1,443.90
		\$ 12,995.10

Special Nett Items

- | | | |
|---|-----------------------------------|---------------------|
| 1 | Front headlamp solar film sticker | \$ 11 150.00 X |
| 1 | Front grille assy | \$ CNE 1,500.00 650 |
| 1 | Front bumper lower lid | \$ NZ 850.00 X |
| 1 | Front number plate with holder | \$ SW 150.00 X |
| | | \$ 2,650.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N

S/N.	Labour Charges		
1	To check wiring and reset headlamps focusing.	\$	80.00 20
2	To remove and refit ^{replace} rear reverse sensor.	\$	180.00 50
3	To remove, refit air-con condenser, refill gas & conduct leakage test.	\$	180.00 X
4	To apply undercoating.	\$	150.00 X
5	Panel beating.	\$	1,500.00 580
6	To re-spray painting on the affected areas.	\$	1,400.00 800
7	To diagnose erase fault memory after repair.	\$	450.00 80
		\$	<u>3,940.00</u>

Grand Total : \$ 19,585.10

P-10153-45
102
P-9138-10
S.N-650
L-1530
11/3/8/0
202
2024