

SERVE YOU MOTOR PTE LTD
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com

Steve (LKK)
12/07/22
Without Prejudice
6 days
L/S
Resurvey After Spray

INSURANCE: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

OWNER / COMPANY: A & S TRANSIT PTE LTD

Registration no. : PA 9476 G / HIGER KLQ6109GQ 6.7 M/T ABS TURBO

Date : 29-Jun-22

Date of accident: 28/6/2022

Quotation No. : 28062022

S/N	Qty	ITEM	AMOUNT
-----	-----	------	--------

LIST ITEMS

1	1	Compartment door with grill (Engine)	\$ 2,560.00	×	R
2	1	Rear Bumper Side	\$ 800 ✓ 880.00		DD
3	1	Rear Top Rh corner Pillar with griller	\$ 2800 ✓ 3,280.00		DD
4	1	Rear tail gate	\$ 3,380.00	×	R
5	1	Rear tail gate inner lock	\$ 180.00	×	NN
6	1	Rear tail gate outer handle	\$ 240.00	×	NN
7	1	Rear number plate lamp	\$ 180.00	×	NN
8	1	Rear bumper	\$ 2,280.00	×	R
9	1 2	Rear bumper bracket \$280 each	\$ 280 ✓ 560.00		
10	1 2	Rear bumper fog lamp (reflector) \$288 each	\$ 95 ✓ 576.00		MIS
11	2	Rear number plate lamp \$118 each	\$ 236.00	×	NN
12	1	Rear (RH) top reflector lamp	\$ 980.00	✓	BR
13	1	Rear lamp RH Lamp	\$ 750.00	✓	BR
14	1	Rear number plate	\$ 68.00	×	NN
15	1	Rear exhaust tail pipe	\$ 384.00	×	NN
16	1	Rear cover inner lock (rear RH glass inner trim)	\$ 284.00	✓	TN
17	1	Rear windscreen glass	\$ 2880 ✓ 3,600.00		BR
18	1	Rear windscreen rubber (rear RH glass)	\$ 500 ✓ 850.00		NEC
19	1	Rear windscreen glass moulding	\$ 450 ✓ 650.00		NEC
			\$21,918.00		9819
			LESS: 10%		-10%
			Total:		\$19,726.20 8837.10

SPECIAL NETTS ITEMS

1	1	LOGO	\$88.00	80 ✓	NEC
---	---	------	---------	------	-----

LABOUR & MISC CHARGES

1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,800.00	2500 ✓	
2		To dismental and refit rear windcreen glass for replacement.	\$ 680.00	✓	
3		Supply and provide necessary multi-purpose material / items to respray on accident damaged portion spray paint multi-purpose.	\$ 2,200.00	1900 ✓	
4		Supply and provide necessary material / items to replace the multi art design logo on accident damaged portion.	\$ 1,680.00	550 ✓	
5		To special vacuum the interior passenger seats to remove the glass debris	\$ 350.00	100 ✓	

TOTAL

\$7,710.00 5810

Total Parts and Labour Cost of Repair 14,647.10 \$27,524.20

L/S - 11,717.68
 = 11,700