

ASS. REC. BY:

REF:

C72/ 22008210/KC

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKU 7163B

Yr Regn:

08, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer CIA 180

c.c

1595

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

118753

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD1173422N234969

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

25/6/22

D.O.I.

4/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA & EH not ready

14/7 6:15pm @ 8300d Cash (Red. 6759.10, 45%)

4/8 12:09pm Spoken to Anthony, confirmed the estimate should use LH Express not Massive Trading.

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

8300

Massive Trading & Auto

Blk 5034 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Chua Hui Kiang Angeline
Blk 256 Compassvale Road
#14-684
Singapore 540256

W001173422

Not Authorized
11 Sep @ 8300h
Resurvey After Paint
5 days

Vehicle No : SKU 7163 B
Make/Model : Mercedes Benz C 180
Year : 2015

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front n/s headlamp	2632.90	mycm	\$2,895.00	✓	
1 pc	Front bumper	1421.95	cm	\$1,568.00	✓	
1 pc	Front bumper inner bracket		in	\$155.00	✓	
1 pc	Front bumper reinforcement		in	\$685.00	✓	
1 pc	Front bumper sponge		in	\$165.00	✓	
2 pcs	Front n/s bumper sensor	262.00	short	\$285.00	✓	
1 pc	Front bumper sensor control unit		in	\$570.00	✓	
1 pc	Front bumper lower grille		cm	\$455.00	✓	
1 pc	Front grille	692.10	cm	\$255.00	✓	
1 pc	Front grille centre garnish		cm	\$765.00	✓	
1 pc	Front grille emblem		in	\$265.00	✓	
1 pc	Front no plate holder		in	\$75.00	✓	
1 pc	Rear end panel		in	\$65.00	✓	
1 pc	Rear end panel inner garnish		mycm	\$865.00	✓	
1 pc	Rear bumper		Bul/cm	\$176.00	✓	
1 pc	Rear bumper inner bracket		ori	\$1,377.00	✓	
1 pc	Rear lower bumper		nd/cm	\$105.00	✓	
1 pc	Rear bumper reinforcement	480	in	\$285.00	✓	
1 pc	Rear bumper lower chrome garnish	310.80	in	\$680.00	✓	
1 pc	Rear bumper lower cover		cm	\$495.00	✓	
1 pc	Rear bumper lower cover		Di's/cm	\$195.00	✓	
2 pcs	Rear bumper side retainer		\$115.00	in	\$230.00	✓
1 pc	Rear o/s tail-lamp	795	cm	\$853.00	✓	
2 pcs	Rear o/s bumper reverse sensor	262.00	short	\$285.00	✓	
				\$570.00	✓	
				\$13,749.00		
				Less 10 %	\$1,374.90	
					\$12,374.10	

S Nett

1 pc Front no plate

in \$40.00 ✓
balance c/f \$12,414.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SKU 7163 B

balance b/f \$12,414.10

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

\$1,000.00 *600*

To putty and spray paint

\$1,000.00 *660*

Check & reconnect wiring.

\$45.00 *40*

To respray anti-rust proofing treatment

na \$120.00 *X*

Remove/repair and realign rear exhaust silencer.

na \$200.00 *X*

Remove/renew rear bumper reverse sensor and to reset to factory specification.

\$280.00 *150*

Total

\$15,059.10

LKK Auto Consultants hence notify the Repairer of the following:

- To respray before/after spray painting
- To display damaged parts during respray
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modifications are allowed
- Subsequent work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____