

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62320
Date Estimated : 29/06/2022
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chew Mun Kit
60 Choa Chu Kang Ave 5
#12-03

Singapore 688191

- ACCOUNT - 158

Longpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6868H	WBATR120X0LC94446	30/10/2018	X3 sDrive20i	93987

DESCRIPTION	VALUE
To replace front bumper, front right fender, bonnet and wheel arch trim.	2550 ✓ 5,100.00
To respray front bumper, front right fender, bonnet and wheel arch trim.	3482 ✓ 4,342.00
To carry out body cavity preservation. (Per panel).	226 ✓ 236.00
To replace right headlight.	456 ✓ 481.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 ✓ 177.00
To check electrical wiring system at the front a sections for proper function including adjustment of headlights.	280 ✓ 295.00
To supply front emboss number plate.	83.00
Sundries.	150.00 ✓

Total Labour 1: 10,864.00

DESCRIPTION	QTY	PRIC	VALUE
FRT RH SIDE PANEL	1	952.05	952.05 ✓
BONNET	1	1,929.95	1,929.95 ✓
RH BOTTOM SIDE PANEL BRACKET	1	42.45	42.45 ✓
FRT RH 2 SIDE PANEL BRACKET	1	42.45	42.45 ✓
FRT RH 3 SIDE PANEL BRACKET	1	42.45	42.45 ✓
FRT BUMPER TOP CARRIER	1	860.45	860.45 ✓
FRT BUMPER BOTTOM CARRIER	1	473.25	473.25 ✓
FRT RH ADAPTER	1	73.10	73.10 ✓
GRILLE AIR INLET MIDDLE	1	121.15	121.15 ✓
FRT BUMPER TOWING FLAP EYE PAINTED	1	67.55	67.55 ✓



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62320
Date Estimated : 29/06/2022
Prepared By : Jack Ng Guo Ming

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6868H	WBATR120X0LC94446	30/10/2018	X3 sDrive20i	93987

DESCRIPTION	QTY	PRIC	VALUE
LH AIR CURTAIN ? × NN	1	49.55	49.55
RH AIR CURTAIN ? BR	1	49.55	49.55
FRT BUMPER RH TRIM CUT	1	58.95	58.95
FRT SHOCK ABSORBER (M) BR	1	76.15	76.15
FRT BUMPER PANEL PRIMED (M/PMMA) BR	1	1,738.90	1,738.90
FRT BUMPER COVER BR (M-h pleu huck g-r-k)	1	238.65	238.65
RH SIDE GRILLE OPEN BR	1	136.30	136.30
FRT RH GRILLE (BASIS) CUT	1	132.90	132.90
FRT NUMBER PLATE CARRIER CUT	1	89.40	89.40
FRT RH WHEEL ARCH TRIM PRIMED (M) BR	1	302.95	302.95
FRT RH WHEEL ARCH TRIM (M) ? BR	1	129.85	129.85
RH HEADLIGHT LED AHL HIGH (ICON LIG) BR	1	4,345.35	4,345.35

Total Parts : 11,953.35

Steve (LKK)
25/7/22, 10:30a

W L
P/P
M PL Y
8 7 4

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before and after painting
 - To repair and/or replace part(s) during resurvey
 - All surveys are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	10,864.00
Parts	:	11,953.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,597.21
Grand Total	:	24,414.56

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 62320**
Date Estimated : **29/06/2022**
Prepared By : **Jack Ng Guo Ming**

- ESTIMATE REPAIR FOR -
Chew Mun Kit
60 Choa Chu Kang Ave 5
#12-03

Singapore 688191

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6868H	WBATR120X0LC94	30/10/2018	X3 sDrive20i	98463

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# Additional labour to replace bumper carrier, intake duct, air duct top and bottom, air duct top radiator, wheel arch trim & attachment	850.00	0.00	850.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# INTAKE DUCT	98.05	1.00	0.00	98.05 ✓ BR
# RH GUIDE BUMPER	54.55	1.00	0.00	54.55 ✓ BR
# FRT BUMPER RH INSERT	54.55	1.00	0.00	54.55 ✓ BR
# FRT RH FOG LAMP SUPPORT	67.15	1.00	0.00	67.15 ✓ BR
# EMBLEM GROMMET	0.95	2.00	0.00	1.90 ✓ NEC
# PLAQUE 82MM	72.85	1.00	0.00	72.85 ✓ NEC
# EMBLEM (M)	83.80	1.00	0.00	83.80 ✓ NEC
# AIR DUCT TOP	225.25	1.00	0.00	225.25 ✓ BR
# AIR DUCT BOTTOM	146.65	1.00	0.00	146.65 ✓ BR
# RH HEADLIGHT MOUNTING	238.45	1.00	0.00	238.45 ✓ BT
# AIR DUCT RADIATOR TOP	107.50	1.00	0.00	107.50 ✓ BR
# AIR DUCT RADIATOR BOTTOM	107.50	1.00	0.00	107.50 ✓ BR
# FRT RH BRAKE AIR DUCT	66.05	1.00	0.00	66.05 ✓ BR
# RH WHEEL ARCH BRAKE AIR DUCT	66.05	1.00	0.00	66.05 ✓ BR
# EXPANDING RIVET BLACK	1.40	12.00	0.00	16.80 ✓ NEC
# HORN LOW PITCH	85.35	1.00	0.00	85.35 ✓ BR
# RH FOG LAMP LED	490.95	1.00	0.00	490.95 ✓ BR
# LABEL COOLANT 550+/-10G	25.00	1.00	0.00	25.00 ✓ NEC

SUPPLEMENTARY ITEMS

Total Labour :	850.00
Total Parts :	2,008.40
Total Labour & Parts :	2,858.40
Deduction for Excess :	
Total Repair Costs less Excess:	2,858.40
GST @7%:	200.09
Grand Total :	3,058.49

CAR RENTAL=\$1027.20
GIA SEARCH FEE=\$2.00