



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22006214/Ucy3m4 Date: 22/07/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1629R	Veh. Inspected	GBL 892E
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/06/22/7032	Excess (\$)	0.00
	Assign From	ANA MAGNAYE	Assign Date	29/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE 2.8 (A)	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	GDH2011052224	Colour	SILVER
	Odometer	42238 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/80 R15	BRIDGESTONE	5 mm
	L/H Front Tyre	195/80 R15	BRIDGESTONE	5 mm
	R/H Rear Tyre	195/80 R15	DUNLOP	5 mm
	L/H Rear Tyre	195/80 R15	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/06/2022	Inspection Date	29/06/2022
	Survey held at	15 KAKI BUKIT ROAD 4 #01-05/53 BARTLEY BIZ		
	Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	