

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG: 200707743D GST REG: 200707743D

hence notify
the Repairer of the following:
• To resurvey after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

29-Jun-22

ESTIMATE REPAIR BILL FOR MAZDA 6 REGN NO: SMF 9732 B

1 pc Front bumper *MT 1212 40*
1 pc Front bumper n/s side bracket *MC 600*
1 pc Front n/s fender *DI 186*
1 pc Front n/s fender inner shield *net*
1 pc n/s headlamp *SC 3200*

Acknowledged by Repairer
Signature:
Date:

Less 20%

S/nett

1 set	Front bumper clips	\$	50.00	<i>30rec</i>
1 set	Front n/s fender inner shield clips	\$	50.00	<i>30rec</i>
	Sundry	\$	50.00	<i>Amn</i>
	To dismantle and refit front reverse sensor and check wiring	\$	80.00	<i>30</i>
	To check wheel alignment	\$	80.00	<i>60</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel etc	\$	700.00	<i>400</i>
	To putty and spray painting on front bumper, front n/s fender	\$	600.00	<i>500</i>
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	<i>30</i>
		\$	1,730.00	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

F: 4200 4/5
P.D: 4

Thuan
82235767
89/6/22 1615
P/P 11 days up