

**RW AUTOMOTIVE APPRAISERS SERVICES**

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

JP/DS/22/3151/SLC

Sng Yeow Boon, Henry
c/o Soon Lee Choon Auto Services Pte. Ltd.
Blk 5032, Ang Mo Kio Industrial
Park 2, #01-283
Singapore 569535

Report No : RW/0031/22TP
Date : 04.06.2022

VEHICLE INSPECTION REPORT**REFERENCE**

Requested by : Workshop, owner's behalf
Date of Request : 31.05.2022
Date of Accident : 25.05.2022
Date of Inspection : 31.05.2022
Inspected at : Soon Lee Choon Auto Services Pte. Ltd.
Blk 5032, Ang Mo Kio Industrial Park 2
#01-283, Singapore 569535

VEHICLE DETAILS

Vehicle No.	: SFH 5000 D	Make & Model	: Mercedes C180
Year Make	: 2017	Colour	: Red
Engine No.	: 27491030691982	Chassis No.	: WDD2050402R199678
Engine Capacity	: 1595 cc	Mileage	: 114,128 km
Air-Con	: Yes	Radio/CD/Cassette	: Yes
Seat Belt	: Yes	Rims	: Sport

GENERAL CONDITION OF VEHICLE

General Condition	: Good	Modification	: Nil
Brakes	: Serviceable	Handbrake	: Serviceable
Steering	: Serviceable		

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Rim</u>	<u>Tread Balance</u>
Front Right	Continental	225/50 R17	Sport	6 mm
Front Left	Continental	225/50 R17	Sport	6 mm
Rear Right	Continental	225/50 R17	Sport	6 mm
Rear Left	Continental	225/50 R17	Sport	6 mm

ASSESSMENT

	<u>Repairer's Estimate</u>	<u>Recommendation</u>
Spare Parts	: \$ 3,846.60	\$ 2,110.50
Labour Charges	: \$ 1,320.00	\$ 1,000.00
Paint Work	: \$ 1,000.00	\$ 700.00
Towing Charges	: \$ -	\$ -
Total	: <u>\$ 6,166.60</u>	<u>\$ 3,810.50</u>
Recommend lump sum repairs	: \$ 3,050.00	
Reduction	: <u>\$ 3,116.60</u>	
Estimated Period Required for Repair	: <u>3 days</u>	

**RW AUTOMOTIVE APPRAISERS SERVICES**

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

JP/DS/22/3151/SLC

Page : 1

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SFH 5000 D

Report No.: RW/0031/22TP

<u>S/No</u>	<u>QTY</u>	<u>Description</u>	<u>Condition/ Remarks</u>	<u>Repairer's Estimates</u>	<u>My Recommendation</u>
-------------	------------	--------------------	-------------------------------	---------------------------------	------------------------------

REPLACEMENT OF DAMAGED PARTS

1)	1	Rear bumper	Distorted	\$ 1,362.00 N	\$ 1,362.00
2)	1set	Rear bumper clips	Necessary	\$ 50.00 N	\$ 50.00
3)	2	Rear bumper side holders	Necessary	\$ 178.00 N	\$ 178.00
4)	1	Rear bumper reinforcement	Repairable	\$ 589.00 N	\$ -
5)	1	Rear bumper tow cover	Serviceable	\$ 58.00 N	\$ -
6)	1	Rear bumper lower garnish	Distorted	\$ 385.00 N	\$ 385.00
7)	1	Rear bumper lower garnish chrome moulding	Cut	\$ 185.00 N	\$ 185.00
8)	1	Rear bumper centre bracket	Serviceable	\$ 282.00 N	\$ -
9)	4	Rear reverse senso	Serviceable	\$ 1,000.00 N	\$ -
10)	1	Rear 'Mercedes Benz' logo	Necessary	\$ 55.00 N	\$ 55.00
11)	1	Rear 'C180' emblem	Necessary	\$ 82.00 N	\$ 82.00
12)	1	Rear 'Cycle & Carriage' logo	Necessary	\$ 48.00 N	\$ 48.00
				\$ 4,274.00	\$ 2,345.00
Less 10%				\$ 427.40	\$ 234.50
				\$ 3,846.60	\$ 2,110.50
Total (Parts):				\$ 3,846.60	\$ 2,110.50

LABOUR CHARGES

13)	Panel beat rear end panel and rear boot lid. Straighten rear left chassis. Remove and replace all damaged parts.	\$	800.00	\$	600.00
14)	Check lightings and wiring.	\$	60.00	\$	40.00
15)	Remove and reinstall rear upholstery, cushion seats and roof lining to enable repair.	\$	150.00	\$	120.00
16)	Remove and reinstall rear reverse sensors.	\$	150.00	\$	120.00
17)	Rust proofing treatment on affected area.	\$	160.00	\$	120.00
18)	Spray painting on affected area.	\$	1,000.00	\$	700.00
Total (Labour):		\$	2,320.00	\$	1,700.00

Total:	\$ 6,166.60	\$ 3,810.50
--------	-------------	-------------



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

JP/DS/22/3151/SLC

Page : 2

Vehicle No: SFH 5000 D

Report No.: RW/0031/22TP

POINT OF IMPACT

At the rear portion of the vehicle.

RECOMMENDATION

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$3,810.50.

CONCLUSION

The repairer has agreed to undertake repairs at a lump sum of \$3,050.00 corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE

RICHARD WONG
(Licensed Appraiser)



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

JP/DS/22/3151/SLC

Vehicle No: SFH 5000 D

Report No: RW/0031/22TP



Vehicle No: SFH 5000 D

Report No: RW/0031/22TP




Vehicle No: SFH 5000 D



Vehicle No: SFH 5000 D

Report No: RW/0031/22TP



Vehicle No: SFH 5000 D

Report No: RW/0031/22TP




Vehicle No: SFH 5000 D

Report No: RW/0031/22TP



Vehicle No: SFH 5000 D

Report No: RW/0031/22TP



Vehicle No: SFH 5000 D

Report No: RW/0031/22TP



Report No: RW/0031/22TP

Vehicle No: SFH 5000 D



Vehicle No: SFH 5000 D

Report No: RW/0031/22TP



Vehicle No: SFH 5000 D

Report No: RW/0031/22TP



Vehicle No: SFH 5000 D

Report No: RW/0031/22TP

