



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR XE6892S

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 56191
Reg No/Reg Date XE6892S / 01/12/2021
Date In/Mileage / 1468
Chassis No W1T964014205184953
Engine No 936912C0233468
Make/Model MBCV/Arocs 2630 6X4 3900
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	01/06/2022/ 11:39	PC	610 / Philip Cheong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 00940101 TO REMOVE & REPAIR FRONT BUMPER, FRONT BUMPER CENTRE GRILLE FRONT STEP CENTRE GARNISH, FRONT HEADLAMP, FRONT STEP PANEL BRACKET, BALE FRONT CABIN PUMP/BRACKET REFORCEMENT END COVER END COVER AND FRONT STEP LOWER GARNISH BRACKET				4560.00
A 00940101 TO REMOVE & REFIT WIRE, LIGHTING AND OIL PIPE				450.00
A 00940101 TO PUTTY & SPRAY PAINTING				1980.00
M END CAP - <i>Art (Bumper end cap LH)</i>	2.00	41.78	00.00	83.56
M CARRIER - <i>MIS (Step time bracket LH)</i>	1.00	612.60	00.00	612.60
M STEP PLATE - <i>OR (Step Plate)</i>	1.00	860.05	00.00	860.05
M BRACKET - <i>OR (Step Plate)</i>	1.00	255.27	00.00	255.27
M BRACKET - <i>OR (Step Plate)</i>	1.00	231.93	00.00	231.93
M STEP PLATE - <i>OR (Step lower bracket)</i>	1.00	45.83	00.00	45.83
M ENTRANCE - <i>BR</i>	1.00	622.63	00.00	622.63
M FRONT FOG LAMP - <i>BR</i>	1.00	547.46	00.00	547.46
M COVER FRAME - <i>BR (Head lamp bracket)</i>	1.00	144.19	00.00	144.19
M BUMPER, FRONT - <i>CUT (Head lamp bracket)</i>	1.00	733.11	00.00	733.11
M BRACKET - <i>BR (Head lamp bracket)</i>	1.00	188.89	00.00	188.89
M FACING - <i>MIS (Head lamp bracket)</i>	1.00	75.83	00.00	75.83
M FRONT SPOILER - <i>OR (LH lower)</i>	1.00	343.98	00.00	343.98
M LAMP UNIT - <i>OR (Head lamp)</i>	1.00	1143.84	00.00	1143.84
M EXPANSION RIVET	2.00	3.90	00.00	7.80

Steve CLKK
30/6/22, 11:00

OD-NLW
EXCPT - ?

PP

LY BL Y

Confirmed & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Authorized signatory and company stamp

4 45
7% GST on 12886.97

Nett 12,886.97
Total Payable 13,789.06

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center
209 Pandan Gardens
Singapore 609339
Tel: (65) 67714389
Fax: (65) 67756310
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG