



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0526/2022/JT
DATE : 25-Jun-22
WIP : 30139

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/06/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. CHEONG MENG YONG
ADDRESS : 30 EASTWOOD ROAD
#02-14, FAIRMOUNT CONDOMINIUM
SINGAPORE 486365
TELEPHONE : HP +65 93364509
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070030452-02
VEHICLE NO : **SLP 1648 Z**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFSI S-TRONIC
MODEL YEAR : 27/2/2020
ENGINE NO : CZD 890178
CHASSIS NO : WAUZZZF31L1063087
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Jun-22
PLACE OF ACCIDENT : EAST COAST ROAD (OUTSIDE SPRINGVALE
CENTRE SHOPPING MALL)



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 1648 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓	\$ 1,600.00 500	500
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS. ✓	\$ 4,000.00 1500	550 x 2 = 1100 Arch Trim = 200 x 2 = 400
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,672.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 1648 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1	\$ 1,585.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 433.00	+
3	FRONT BUMPER CLOSING ELEMENT - RH ?	1	\$ 66.00	?
4	FRONT BUMPER TRIM <i>new</i>	1	\$ 396.00	+
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 242.00	+
6	FRONT PARKING AID SENSOR SUPPORT - RH INNER <i>new</i>	1	\$ 29.00	+
7	FRONT BUMPER GRILLE COVER <i>new</i>	1	\$ 58.00	+
8	FRONT BUMPER CLOSING ELEMENT <i>?</i>	1	\$ 212.00	?
9	FRONT BUMPER SPOILER <i>ut</i>	1	\$ 850.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 171.00	+
11	FRONT BUMPER TRIM - RH <i>new</i>	1	\$ 182.00	+
12	FRONT PARKING AID SENSOR SUPPORT - RH OUTER <i>new</i>	1	\$ 29.00	+
13	RADIATOR GRILLE <i>new ?</i>	1	\$ 2,135.00	ut ?
14	RADIATOR STRIKER PLATE ?	1	\$ 271.00	?
15	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 256.00	+
16	RADIATOR GRILLE COVER <i>new</i>	1	\$ 271.00	+
17	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 114.00	?
18	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 974.00	+
19	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 137.00	+
20	FRONT BUMPER GUIDE SECTION- RH <i>new</i>	1	\$ 43.00	+
SUB TOTAL SPARE PARTS		:	\$ 8,454.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 1648 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AIR COND STICKER <i>3 new</i>	1	\$ 9.00	+
22	CAUTION STICKER	1	\$ 16.00	+
23	FRONT PARKING AID SENSOR <i>3 new</i>	2	\$ 530.00	+
24	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00	+
25	HORN - RH <i>3 new</i>	1	\$ 145.00	+
26	HORN SUPPORT - RH	1	\$ 25.00	+
27	HEADLIGHT MOUNTING - RH <i>new</i>	1	\$ 132.00	+
28	HEADLIGHT - RH <i>crack d</i>	1	\$ 5,952.00	✓
29	LIFT CYLINDER - RH <i>3 new</i>	1	\$ 231.00	+
30	LIFT CYLINDER HOSE	1	\$ 92.00	+
31	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 1,132.00	✓
32	FRONT WHEEL HOUSING LINER - RH <i>new</i>	1	\$ 260.00	+
33	FRONT WHEEL HOUSING LINER COVER - RH <i>new</i>	1	\$ 18.00	+
34	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - RH <i>new</i>	1	\$ 22.00	+
35	RADIATOR AIR GUIDE - RH <i>3 new</i>	1	\$ 43.00	+
36	RADIATOR AIR GUIDE - UPPER <i>new</i>	1	\$ 48.00	+
37	FRONT NO PLATE ?	S/N	\$ 60.00	?
38	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 17,579.00	
TOTAL LABOUR CHARGES		:	\$ 6,672.00	
GRAND TOTAL		:	\$ 24,251.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *29/06/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT