



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0518/2022/JT
DATE : 23-Jun-22
WIP : 29591

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 29/6/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAY KIANG HIONG
ADDRESS : 8 GRACE WALK
SINGAPORE 557732
TELEPHONE : HP +65 98255502
TYPE OF CLAIM : OWN DAMAGED CLAIM
POLICY NO : 7210093220
VEHICLE NO : **SLS 5030 M**
MODEL CODE : AUDI E-TRON SB ADVANCE
MODEL YEAR : 3/9/2021
ENGINE NO : EAS 076077
CHASSIS NO : WAUZZZGE1MB042039
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-22
PLACE OF ACCIDENT : IN FRONT OF 8 GRACE WALK

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 5030 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00 ✓ 250	
3	TO DEACTIVATE AND REACTIVATE HIGH VOLTAGE SYSTEM FOR VEHICLE.	S/N \$ 480.00 ✓	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,600.00 ✓ 1200	
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER RHS, BOTH FRONT FENDERS, BONNET, HINGES AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 5,500.00 ✓ 2200	600x3 = 1800 Air Trim = 200x2 = 400 2200
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	2200
TOTAL LABOUR CHARGES		: \$ 10,702.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 5030 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Rebond</i>	1	\$ 2,896.00	✓	
2	FRONT BUMPER FIXING PARTS	1	\$ 658.00	+	
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>3 new</i>	1	\$ 248.00	+	
4	FRONT BUMPER GRILLE COVER - RH <i>2 new</i>	1	\$ 39.00	+	
5	FRONT BUMPER FOAM PART - UPPER <i>1 new</i>	1	\$ 150.00	+	
6	FRONT BUMPER FOAM PART - LOWER	1	\$ 125.00	+	
7	FRONT BUMPER FOAM STRIP <i>new</i>	1	\$ 134.00	+	
8	FRONT BUMPER GRILLE - LOWER CENTER <i>2 new</i>	1	\$ 283.00	+	
9	FRONT BUMPER GRILLE - CENTER <i>1 new</i>	1	\$ 171.00	+	
10	FRONT BUMPER CLOSING ELEMENT - LOWER <i>1 new</i>	1	\$ 235.00	+	
11	FRONT BUMPER IMPACT PROTECTION	1	\$ 899.00	+	
12	FRONT BUMPER AIR GUIDE - RH <i>3 new</i>	1	\$ 101.00	+	
13	FRONT BUMPER SPOILER - RH	1	\$ 175.00	+	
14	FRONT BUMPER AIR GUIDE OUTER - RH <i>3 new</i>	1	\$ 58.00	+	
15	FRONT BUMPER AIR GUIDE INNER - RH	1	\$ 45.00	+	
16	FRONT BUMPER TRIM - RH <i>3 new</i>	1	\$ 65.00	+	
17	FRONT BUMPER AIR GUIDE - RH	1	\$ 134.00	+	
18	RADIATOR GRILLE <i>Cracked</i>	1	\$ 2,317.00	✓	
19	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 141.00	+	
20	RADIATOR GRILLE BRACKET	1	\$ 104.00	-	
SUB TOTAL SPARE PARTS		:	\$ 8,978.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 5030 M

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR GRILLE COVER - CENTER <i>Ne m</i>	1	\$ 69.00	+
22	RADIATOR GRILLE CLOSING ELEMENT ?	1	\$ 246.00	?
23	RADIATOR GRILLE COVER - LH / RH ?	2	\$ 122.00	?
24	FRONT BUMPER REINFORCEMENT BEAM <i>3pc</i>	1	\$ 1,451.00	+
25	FRONT BUMPER MOUNTING BRACKET - RH	1	\$ 481.00	+
26	FRONT BUMPER BRACKET - RH ?	1	\$ 87.00	+
27	FRONT BUMPER CROSS MEMBER	1	\$ 464.00	+
28	FRONT BUMPER LOWER COVER	1	\$ 118.00	+
29	FRONT BUMPER TOP COVER <i>De Ben</i>	1	\$ 119.00	✓
30	HYBRID WARNING SIGN <i>Nec</i>	1	\$ 21.00	✓
31	AIR COND STICKER <i>Nec</i>	1	\$ 21.00	+
32	BONNET <i>Dented</i>	1	\$ 5,482.00	✓
33	BONNET ATTACHMENT PARTS <i>nec</i>	1	\$ 217.00	+
34	BONNET HINGE - LH / RH <i>Ne nec</i>	2	\$ 382.00	+
35	BONNET IMPACT PROTECTION - LH / RH / CENTER <i>Nec</i>	3	\$ 134.00	✓
36	BONNET PLENUM CHAMBER COVER ?	1	\$ 222.00	+
37	BONNET STRIKER - LH / RH	2	\$ 268.00	+
38	BONNET RELEASE ELEMENT <i>Not</i>	1	\$ 65.00	+
39	BONNET LOCK MICRO-SWITCH <i>Nec</i>	2	\$ 455.00	+
40	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,488.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 5030 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	BONNET RELEASE CABLE COVER <i>new</i>	1	\$ 11.00	+	
42	FRONT BUMPER TOP COVER - RH OUTER <i>new</i>	1	\$ 114.00	+	
43	HEADLIGHT MATRIX BEAM - RH <i>cracked</i>	1	\$ 8,660.00	✓	
44	RADIATOR AIR GUIDE - RH <i>new</i>	1	\$ 29.00	+	
45	RADIATOR AIR GUIDE - UPPER <i>new</i>	1	\$ 32.00	+	
46	FRONT WINDSCREEN WATER DELECTOR STRIP - LH / RH <i>new</i>	2	\$ 132.00 66	+	
47	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 1,086.00	✓	
48	FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	✓	
49	SUNDRIES <i>?</i>		\$ 400.00	?	
TOTAL SPARE PARTS		:	\$ 29,990.00		
TOTAL LABOUR CHARGES		:	\$ 10,702.00		
GRAND TOTAL		:	\$ 40,692.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian Lim
: 29/08/22 ✓
:
:
:
:
: Not Authorised, 06 Days

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT