

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0518/2022/JT
DATE : 23-Jun-22
WIP : 29591

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 29/6/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

10 days exclude 1 Sunday

Johnny Boo 11 Nov 22

OWNER'S NAME : MR TAY KIANG HIONG
ADDRESS : 8 GRACE WALK
SINGAPORE 557732
TELEPHONE : HP +65 98255502
TYPE OF CLAIM : OWN DAMAGED CLAIM
POLICY NO : 7210093220
VEHICLE NO : **SLS 5030 M**
MODEL CODE : AUDI E-TRON SB ADVANCE
MODEL YEAR : 3/9/2021
ENGINE NO : EAS 076077
CHASSIS NO : WAUZZZGE1MB042039
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-22
PLACE OF ACCIDENT : IN FRONT OF 8 GRACE WALK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 5030 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	450.00	\$ 250.00
3	TO DEACTIVATE AND REACTIVATE HIGH VOLTAGE SYSTEM FOR VEHICLE.	S/N \$	480.00	\$ 480.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,600.00	\$ 1,200.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER RHS, BOTH FRONT FENDERS, BONNET, HINGES AND BOTH FRONT WHEEL ARCH TRIMS.	\$	5,500.00	\$ 2,200.00
6	Added labour	\$	5,400.00	\$ 4,800.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 16,102.00	\$ 9,602.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 5030 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,896.00	\$	2,316.80
2	FRONT BUMPER FIXING PARTS	1	\$ 658.00		
3	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 248.00	\$	198.40
4	FRONT BUMPER GRILLE COVER - RH	1	\$ 39.00		
5	FRONT BUMPER FOAM PART - UPPER	1	\$ 150.00		
6	FRONT BUMPER FOAM PART - LOWER	1	\$ 125.00		
7	FRONT BUMPER FOAM STRIP	1	\$ 134.00		
8	FRONT BUMPER GRILLE - LOWER CENTER	1	\$ 283.00		
9	FRONT BUMPER GRILLE - CENTER	1	\$ 171.00	\$	136.40
10	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 235.00		
11	FRONT BUMPER IMPACT PROTECTION	1	\$ 899.00		
12	FRONT BUMPER AIR GUIDE - RH	1	\$ 101.00		
13	FRONT BUMPER SPOILER - RH	1	\$ 175.00		
14	FRONT BUMPER AIR GUIDE OUTER - RH	1	\$ 58.00		
15	FRONT BUMPER AIR GUIDE INNER - RH	1	\$ 45.00		
16	FRONT BUMPER TRIM - RH	1	\$ 65.00		
17	FRONT BUMPER AIR GUIDE - RH	1	\$ 134.00		
18	RADIATOR GRILLE	1	\$ 2,317.00	\$	1,853.60
19	RADIATOR GRILLE COVER CAP	1	\$ 141.00		
20	RADIATOR GRILLE BRACKET	1	\$ 104.00		
SUB TOTAL SPARE PARTS		:	\$ 8,978.00	\$	4,505.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 5030 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>4,505.20</i>
21	RADIATOR GRILLE COVER - CENTER	1	\$ 69.00		
22	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 246.00		
23	RADIATOR GRILLE COVER - LH / RH	2	\$ 122.00	<i>\$</i>	<i>48.80</i>
24	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,451.00		
25	FRONT BUMPER MOUNTING BRACKET - RH	1	\$ 481.00	<i>\$</i>	<i>384.40</i>
26	FRONT BUMPER BRACKET - RH	1	\$ 87.00	<i>\$</i>	<i>68.88</i>
27	FRONT BUMPER CROSS MEMBER	1	\$ 464.00		
28	FRONT BUMPER LOWER COVER	1	\$ 118.00		
29	FRONT BUMPER TOP COVER	1	\$ 119.00	<i>\$</i>	<i>95.20</i>
30	HYBRID WARNING SIGN	1	\$ 21.00	<i>\$</i>	<i>16.56</i>
31	AIR COND STICKER	1	\$ 21.00	<i>\$</i>	<i>16.56</i>
32	BONNET	1	\$ 5,482.00	<i>\$</i>	<i>4,385.60</i>
33	BONNET ATTACHMENT PARTS	1	\$ 217.00		
34	BONNET HINGE - LH / RH	2	\$ 382.00		
35	BONNET IMPACT PROTECTION - LH / RH / CENTER	3	\$ 134.00	<i>\$</i>	<i>105.92</i>
36	BONNET PLENUM CHAMBER COVER	1	\$ 222.00		
37	BONNET STRIKER - LH / RH	2	\$ 268.00		
38	BONNET RELEASE ELEMENT	1	\$ 65.00		
39	BONNET LOCK MICRO-SWITCH	2	\$ 455.00	<i>\$</i>	<i>182.00</i>
40	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00		
SUB TOTAL SPARE PARTS		:	\$ 10,488.00	<i>\$</i>	<i>9,809.12</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 5030 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 9,809.12</i>
41	BONNET RELEASE CABLE COVER	1	\$ 11.00	
42	FRONT BUMPER TOP COVER - RH OUTER	1	\$ 114.00	
43	HEADLIGHT MATRIX BEAM - RH	1	\$ 8,660.00	<i>\$ 6,928.00</i>
44	RADIATOR AIR GUIDE - RH	1	\$ 29.00	
45	RADIATOR AIR GUIDE - UPPER	1	\$ 32.00	
46	FRONT WINDSCREEN WATER DELECTOR STRIP - LH / RH	2	\$ 132.00	<i>\$ 52.80</i>
47	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,086.00	<i>\$ 868.80</i>
48	FRONT NO PLATE	S/N	\$ 60.00	<i>\$ 60.00</i>
49	Added parts		<i>\$ 2,010.00</i>	<i>\$ 1,605.92</i>
50	SUNDRIES		\$ 400.00	<i>\$ 41.60</i>
TOTAL SPARE PARTS			\$ 32,000.00	\$ 19,366.24
TOTAL LABOUR CHARGES			\$ 16,102.00	\$ 9,602.00
GRAND TOTAL			\$ 48,102.00	\$ 28,968.24

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-05/10/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0518/2022/JT 28-Jul-22 CHANG 1 of 1 SLS 5030 M AUDI E-TRON SB ADVANCE
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND REINSTALL AIRCON CONDENSE AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,800.00	\$ 1,800.00
2	TO CARRY OUT VACUUM AND REGAS FOR R1234yf.	S/N \$ 1,200.00	\$ 1,200.00
3	TO DISMANTLE AND RENEW FRONT LOCK CARRIER, ALIGN TO POSITION.	\$ 2,400.00	\$ 1,800.00
		\$ 5,400.00	\$ 4,800.00
<u>Parts</u>			
1	FRONT BUMPER GUIDE - RH	\$ 50.00	\$ 39.52
2	FRONT LOCK CARRIER	\$ 1,283.00	\$ 1,026.40
3	FRONT FENDER BRACKET - RH	\$ 76.00	\$ 60.72
4	SPREADER RIVET	\$ 76.00	\$ 60.80
5	RADIATOR AIR GUIDE - UPPER	\$ 88.00	\$ 69.68
6	ADJUSTING ELEMENT	\$ 140.00	\$ 111.68
7	COOLANT	\$ 297.00	\$ 237.12
	materials	\$ 2,010.00	\$ 1,605.92
	labour	\$ 5,400.00	\$ 4,800.00
	GRAND TOTAL	\$ 7,410.00	\$ 6,405.92

For Premium Automobiles Pte Ltd

Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT