Sec. 11

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD3844X

Make : HYUNDAI

Model : IONIQ(G3) Date: 07.06.2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER	Service and Comment of the Comment o	200 marriago (200 m.)	RY \$459.40
750	REAR BUMPER CLIPS			are \$22.00
	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
l	REAR BUMPER REFLECTOR LAMP RH			\$41.45
	REAR BUMPER REINFORCEMENT			7 \$394.80
	SUB TOTAL LESS 20% DISCOUNTED TOTAL REAR BUMPER REVERSE SENSOR REAR BUMPER ADVERTISEMENT STICKER REAR FENDER ADVERTISEMENT STICKER RH REAR FENDER ADVERTISEMENT STICKER LH			\$1,368.90 \$273.78 \$1,095.12 ? \$180.00 WL \$50.00 WE \$100.00
	Labour Charge PANEL BEATING SPRAY PAINTING CHARGE REMOVE/REFIX REVERSE SENSOR TOTAL LABOUR ESTIMATE TOTAL			\$430.00 \$\$\\$\$400.00 \$\$\\$\$300.00 \$\\$\$80.00 \$780.00 \$2,305.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tarphi 92495749

W/ Hb/220320

US Rising offer report

2 ders

farght Olhhando-un

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prajudice" basis
- No illegal modification(5) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 57970 ! Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 363 Sin Ming Drive Singapore 575717

Date/Time: 07.06.2022 14:12

Page: 1

Team: JC NO.305518850 ARC Repair TP(CLSO)1 JOB CARD Sales Order: 4254185 :USTOMER MILEAGE REGN NO.: SHD3844X COMFORT TRANSPORTATION PTE LTD 1R/MS **FUEL** 7010045 HYUNDAI SUSTOMER NO. TOTAL DRIVE NOBERS 383 SIN MING DRIVE E......F 07.06.2022 11:15 MODEL IONIQ(G2) Singapore SINGAPORE 575717 65508755 TARGET DATE EL. (R) YR OF MANU. 11.12.2018 (O) (P) COMPLETION DATE/TIME: CHASSIS CODE KMHC851CVKU122342 ISCOUNT CARD NO.

JOB DESCRIPTION


Accident Date: 04.06.2022

NATURE: 3P 04.06.2022

S/NO

LABOR CODE

DESCRIPTION



	•		
HECKED & PASSED OUT BY:			
SERVICE ADVISOR	CUSTOMER'S SIGNATURE		
nowledgement Slip	Exit Pass		
le: lo.: SHD3844X YY	ehicle No.: SHD3844X		
e returned to Service Reception upon collection	Name of Service Advisor To be kept by Security Guard		