

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

NAGAPPAN MANIKANDAN
BLK 61 CIRCUIT ROAD #04-217
SINGAPORE 370061

Contact : 94502491

TP AXA
Ceilia.

TAX INVOICE

Repair Code : CLM15575

Date in : 04/07/2022

Vehicle Num. : SMX3273D

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW516154377/2ZR2H32983

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehid</i>	1	515.10	✓ 515.10
REAR BUMPER LOWER LID <i>Dehid</i>	1	396.90	✓ 396.90
REAR BUMPER REFLECTOR L/R <i>new LH cracked</i>	2	41.40	41.40 82.80
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	353.10	✓ 353.10
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	140.50	✗ 281.00
REAR BUMPER TOW HOOK COVER <i>new</i>	1	23.40	✗ 23.40
REAR BUMPER UNDER COVER (CENTER) <i>torn</i>	1	244.00	✓ 244.00
REAR BUMPER UNDER COVER LH <i>torn</i>	1	256.50	✓ 256.50
REAR BUMPER UNDER COVER RH <i>new</i>	1	256.50	✗ 256.50
REAR END PANEL <i>Repair</i>	1	689.70	✗ 689.70
REAR END PANEL ANTENNA SENSOR <i>green</i>	1	76.30	✗ 76.30
REAR END PANEL INNER TOP GARNISH	1	178.70	✗ 178.70
REAR TAILGATE MECHANISM LOCK <i>green</i>	1	495.40	✗ 495.40
REAR TAILGATE WEATHER STRIP	1	394.70	✗ 394.70
Subtotal before discount			4,244.10
Percentage discount 25%			1,061.03
Sub-total 1			3,183.08
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30 80.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

NAGAPPAN MANIKANDAN
BLK 61 CIRCUIT ROAD #04-217
SINGAPORE 370061

Contact : 94502491

TAX INVOICE

Repair Code : CLM15575

Date in : 04/07/2022

Vehicle Num. : SMX3273D

Model : TOYOTA PRIUS HYBRID 1.8S CVT

Chassis/Eng# : ZVW516154377/2ZR2H32983

REAR BUMPER REVERSE SENSOR	<i>Damaged.</i>	1	280.00	<i>200</i>	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>None</i>	1	40.00	<i>+</i>	40.00
Subtotal before discount					400.00
Percentage discount 0%					0.00
Sub-total 2					400.00
Parts-total					3,583.08

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,720.00
Parts & Labour Total	5,303.08

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Adrian G
h/s 04/07/22*

24 Days

*total: 2375.40
h/s: 1.9K ✓*