

Asia Motorsports Solution Pte Ltd

37A Everitt Road , Singapore 428586

VEHICLE REPAIR ESTIMATE

Vehicle Registration No: GBL1341Y

Date: 29 June 2022

Qty	Description	Condition	Repairer's Estimate
-----	-------------	-----------	---------------------

SPARE PARTS - LIST ITEMS

1	Rear bumper assy	Dented/Warped	584.10 \$ 1,200.00	✓
4 pcs	Rear bumper bracket	Warped/Necessary	88 \$ 375.00	✓
1	Rear bumper retainers	Warped/Necessary	210.20 \$ 385.00	✓
1	Rear bumper upper LH	Warped	\$ 260.00	X
1	Rear bumper step bracket	Warped	242.80 \$ 260.00	✓
1	Rear taillamp RH	Cracked	388.60 \$ 1,150.00	✓
1	Rear taillamp LH	Cracked	388.60 \$ 1,150.00	✓
1	Rear tailgate assy	Dented/Warped	2192.10 \$ 2,245.00	✓
1	Rear tailgate lock actuator motor	Malfunction	345.20 \$ 620.00	✓
1	Rear tailgate lock latch	Malfunction	\$ 380.00	X
1	Rear tailgate lock cover	Bent	105.10 \$ 180.00	✓
1	Rear tailgate weatherstrip	Torn/Necessary	\$ 320.00	✓
1	Rear tailgate outer garnish	Warped	\$ 280.00	✓
1	Rear tailgate inner board	Warped	288.40 \$ 320.00	✓
1	Rear tailgate vehicle lamp (1 set)	Malfunction	\$ 280.00	X
1	Rear tailgate dampers (1 set)	Bent/Necessary	\$ 520.00	X
1	Rear floor panel	Repair	\$ -	X
1	Rear end panel	Dented	801.10 \$ 950.00	✓
1	Rear end panel inner	Dented	845.60 \$ 989.00	✓
1	Rear exhaust pipe muffler	Bent	\$ 600.00	X
			\$ 12,464.00	
			Less 25%	
			\$ 3,116.00	
			\$ 9,348.00	

Not Authorized
here
30/6/22

L/S \$ 6300
6 days
Wholesale After Rep-

Submit to us

Asia Motorsports Solution Pte Ltd

Vehicle Registration No: GBL1341Y

Date: 29 June 2022

SPECIAL NETT ITEMS

1	Rear bumper clips (1 set)	nee	Necessary	\$	120.00	50
1	Rear bumper reverse sensor (1 set)	Shoked/Toon	Necessary	\$	550.00	200
1	Rear logo emblem	nee	Necessary	\$	100.00	45
1	Rear end panel sealant (1 set)	nee	Necessary	\$	150.00	50
1	Rear windscreen sealant (1 set)	nee	Necessary	\$	150.00	40
1	Rear vehicle plate	n 1	Warped/Cracked	\$	180.00	X
1	"70 Km/h" Sticker	nee	Necessary	\$	50.00	10
1	"8 Pax" Sticker	nee	Necessary	\$	50.00	10
1	Rear spare tyre rim	1 1	Bent	\$	280.00	X
1	Rear spare tyre bracket	1 1	Bent	\$	322.00	X
				\$	1,952.00	
Total parts				\$ 11,300.00		

Asia Motorsports Solution Pte Ltd

Vehicle Registration No: GBL1341Y

Date: 29 June 2022

Total cost of parts c/f

\$ 11,300.00

S/No	Description	Repairer's Estimate
------	-------------	---------------------

LABOUR

1	To cut, weld, straighten affected areas and replace damaged parts.	\$ 2,600.00 1000
2	To putty and spray painting the affected areas. Job Allowance.	\$ 2,600.00 850
3	To check rear lighting and wiring.	\$ 140.00 30
4	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 11 280.00 X
5	To apply anti rust proofing to the affected areas.	\$ 300.00 80
6	To remove and install rear windscreen to facilitate the repair	\$ 280.00 120
7	To remove and install rear tailgate assy.	\$ 280.00 60
8	To remove and install taillamp & vehicle license lamp.	\$ 11 280.00 X
9	To remove and install rear vehicle license plate.	\$ 11 280.00 X
10	To remove and install rear bumper assy.	\$ 11 280.00 X
11	To remove and install rear bumper reverse sensor	\$ 280.00 50
12	To remove and install rear end panel assy.	\$ 11 280.00 X
13	To remove and install exhaust system.	\$ 11 280.00 X
14	To install and remove the rear lock components.	\$ 11 280.00 X
15	To check central door lock system.	\$ 11 300.00 X
16	To conduct chassis alignment.	\$ 11 350.00 X

Grand Total:

\$ 20,390.00

P-707980
252
530985
405
2190
7904.88
202
6323

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: