



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2206-346-TG
DATE : 30-Jun-2022
POLICY NO. :
VEHICLE REG. NO. : SGM2292J
VEHICLE MAKE : TOYOTA SIENTA 1.5X A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>✓ BR</i>	1	\$ 481.25	\$ 481.25 <i>✓</i>
3	Rear Bumper Extension (Center)(52151G) <i>(M4K) ✓ CUT</i>	1	\$ 231.10	\$ 231.10 <i>✓</i>
4	Rear Bumper Side (LH/RH) <i>X NN</i>	2	\$ 174.45	\$ 348.90
5	Rear Bumper Side Retainer (LH/RH) <i>X NN</i>	2	\$ 172.00	\$ 344.00
6	Rear Reflector (LH/RH) <i>X NN</i>	2	\$ 182.10	\$ 364.20
7	Rear Reflector Garnish (LH/RH) <i>✓ CUT</i>	<i>21</i>	\$ 191.45	\$ 382.90 <i>156 ✓</i>
8	Rear Tailgate <i>✓ ON</i>	1	\$ 1,212.10	\$ 1,212.10 <i>✓</i>
9	Rear Tailgate Weatherstrip <i>✓ CR4</i>	1	\$ 571.85	\$ 571.85 <i>291 ✓</i>
10	Rear Tailgate Lock <i>✓ BT</i>	1	\$ 571.75	\$ 571.75 <i>341 ✓</i>
11	Rear Tailgate Emblem <i>✓ MC</i>	1	\$ 121.10	\$ 121.10 <i>60 ✓</i>
12	Rear Windscreen Moulding <i>✓ MC</i>	1	\$ 540.00	\$ 540.00 <i>120 ✓</i>
13	Rear End Panel (58307) <i>X R</i>	1	\$ 731.10	\$ 731.10
14	Rear End Panel Outer (58371B) <i>X R</i>	1	\$ 571.75	\$ 571.75
15	Rear End Panel Top Garnish <i>✓ CR4</i>	1	\$ 371.20	\$ 371.20 <i>165 ✓</i>
Total Spare Parts				\$ 6,843.20
SPECIAL NETT				
16	Rear Licence Plate <i>X NN</i>	1	\$ 35.00	\$ 35.00
17	Rear Bumper Clips <i>✓ MC</i>	10	\$ 5.00	\$ 50.00 <i>30 ✓</i>
18	Sealant <i>✓ MC</i>	1	\$ 60.00	\$ 60.00 <i>✓</i>
Total Special Nett				\$ 145.00 <i>70</i>
LABOUR				
19	Spray painting (Rear Bumper, Rear Bumper Side (LH/RH), Rear Tailgate, Rear End Panel)	1	\$ 1,000.00	\$ 1,000.00 <i>401</i>
20	Repair, Refit, Remove and Replace Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00 <i>400</i>
21	Transfer tailgate fitting and window mechanism to new tailgate	1	\$ 80.00	\$ 80.00 <i>50</i>
22	Remove and refit rear windscreen	1	\$ 120.00	\$ 120.00 <i>✓</i>
23	Remove and Refit Rear Bumper Sensor	1	\$ 100.00	\$ 100.00 <i>30</i>
24	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00 <i>30</i>
25	Check and Rectify Electric Wiring	1	\$ 50.00	\$ 50.00 <i>30</i>
Total Labour				\$ 2,450.00 <i>1060</i>
Amount Before Excess				\$ 9,438.20

Estimate prepared by: James Tan
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.

3057.45
-25%
2293.08

70

1060

= 3423.08

L/S - 2738.46
= 2750



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2206-346-TG
DATE : 30-Jun-2022
POLICY NO. :
VEHICLE REG. NO. : SGM2292J
VEHICLE MAKE : TOYOTA SIENTA 1.5X A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.			
			Add GST @ 7%	660.67
			Total Amount Payable	\$ 10,098.87

Steve (LKK)
30/6/22, 12.30p

m 1-
L/S
by M y
4 L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be noted and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: