



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 3154T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u> REAR DOOR RH (NPA) LESS 5% DISCOUNT LESS 25% DISCOUNT <u>LABOUR</u> PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR DOOR RH.} SPRAY PAINT ON AFFECTED AREAS.}	TO REPAIR SEE LABOUR	- - - - 250.00 250.00 500.00	- - - - 250.00 - 250.00
GRAND TOTAL			500.00	250.00
RECOMMENDED COST OF REPAIRS				250.00

Report Ref No. CS/SMO22006245/Kcy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.