

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

S		Affiliated to Federation Internationale Des Experts En Automobile				
_	OMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO22006245/Kcy3m4		
	0 RAFFLES PLAC	E #03-03) TOWERSINGAPORE 048623	Date:	21/07/2022		
			Code:	SMO		
1.	Policy Particulars :- THIRD PARTY CLAIM					
In	nsured Veh.	SMN 1126L	Veh. Inspected	SLP 3154T		
Р	olicy No.		Coverage (\$)	0.00		
С	laim No.	CMTD2202233/AGC	Excess (\$)	0.00		
Α	ssign From	GRACE TEO	Assign Date	30/06/2022		
2. Vehicle Particulars & Condition						
M	lake & Model	BMW 316I (A)	c.c	1598		
E	ingine No.	HIDDEN	Year of Reg.	2013		
С	hassis No.	WBA3A12010J719763	Colour	METALLIC BLACK		
О	dometer	125350 KM	Steering	IN ORDER		
В	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
G	Seneral	GOOD				
3. Conditions of Tyres						
		Size	Make	Balance		
R	H Front Tyre	245/40 R18	GOODYEAR	8 mm		
L	/H Front Tyre	245/40 R18	GOODYEAR	8 mm		
R	A/H Rear Tyre	245/40 R18	GOODYEAR	8 mm		
L	/H Rear Tyre	245/40 R18	GOODYEAR	8 mm		
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S DOOR DENTED.					
D.	DAMAGES SEE DETAILS.					
5.	General Information					
Α	ccident Date	24/06/2022	Inspection Date	30/06/2022		
s	Survey held at	J.E.W AUTO PTE LTD	-			
		60 JALAN LAM HUAT #03-72 CARROS CENTRE SINGAPORE 737869				
5a.	Remarks					
Δ,	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
B	71117100011271110		Estimate Days of Repair			
5b.	<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	Estimate I	Days of Repair			