

ASS. REC. BY:

REF:

Smo / 22008245/KC

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 833k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS _____

Date: _____ Person Contacted: John

Vehicle: IN / OUT

91997483Veh No: SIP 31547 Yr Regn: 07, 13Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Bmw 316i C.C. 1598Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 125350 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 3A12010J 7P763Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 245/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. P mm R/Bal. P mmL/Bal. P mm L/Bal. P mmD.O.A. 24/6/22 D.O.I. 30/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear d/s door dented

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

30/6 8250L Canhw (Rad 250f, 50%)

Date/Time, File Pass to?

☐ : Prell. Report☒ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / (B.I.): (\$

TP.

250f



Estimation

Date 30/06/2022
 Vehicle SLP 3154 T
 Make/Model BMW 316i
 Chassis No.

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	REAR DOOR RH	1	REPAIR	REPAIR
			Total	\$ -
			Less 5%	\$ -
			Total	\$ -

LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	250	\$ 250.00
2	SPRAY PAINT ON AFFECTED AREAS	1	250	\$ 250.00
			Total Labour	\$ 500.00
			Parts Replacement Amount	
			Total Amount	\$ 500.00

NOT WORKING
 1 day
 Repair the paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: