



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22006251/Aqy3e2 Date: 04/04/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKX 5140P	Veh. Inspected	SKB 2345B	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10016067 /CD	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	30/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 523I	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAFP32060C865748	Colour	BRONZE	
Odometer	322502 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	MICHELIN	6 mm	
L/H Front Tyre	245/45 R18	MICHELIN	6 mm	
R/H Rear Tyre	245/45 R18	MICHELIN	6 mm	
L/H Rear Tyre	245/45 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/06/2022	Inspection Date	30/06/2022	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	