



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2302512

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/04/2023
Reference CC6/CTI22006253/Dya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 4531S
Insured Veh. SMZ 5133B
Claim No. SNM22D204580/C02
Policy No. DMPCSNW00068622100
Accident Date 29/06/2022
Inspection Date 30/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22006253/Dya3q2 Date: 20/04/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMZ 5133B	Veh. Inspected	SHD 4531S	
Policy No.	DMPCSNW00068622100	Coverage (\$)	0.00	
Claim No.	SNM22D204580/C02	Excess (\$)	0.00	
Assign From		Assign Date	30/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVLU188323	Colour	BLUE	
Odometer	308741 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DUNLOP	5 mm	
L/H Front Tyre	195/65 R15	DUNLOP	5 mm	
R/H Rear Tyre	195/65 R15	DUNLOP	5 mm	
L/H Rear Tyre	195/65 R15	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/06/2022	Inspection Date	30/06/2022	
Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate			
Repairer	BIFROST AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4531S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BENT / DENTED	2,253.80	2,253.80
2	BONNET HINGE (LH/RH) @\$118.70	SERVICEABLE	237.40	-
1	BONNET MOULDING	NOT NECESSARY	41.40	-
1	BONNET LOCK	SERVICEABLE	127.30	-
1	BONNET INSULATOR	NOT NECESSARY	230.10	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	15.00	-
1	RADIATOR GRILLE NEW MODEL	BROKEN	1,568.60	1,568.60
2	FLAP ASSY ACTIVE AIR UPPER ,(LH/RH) @\$824.60	BROKEN	1,649.20	1,649.20
1	SPEAKER ASSY-VESS	BROKEN	554.40	554.40
1	FRONT NUMBER PLATE GARNISH	DEFORMED	188.00	188.00
1	FRONT BUMPER COVER	CRACKED	481.10	481.10
1	FRONT BUMPER TOP COVER	CRACKED / BROKEN	476.30	476.30
1	FRONT BUMPER SPONGE	TORN	186.90	186.90
1	FRONT BUMPER REINFORCEMENT	DENTED	1,136.70	1,136.70
2	FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH) @\$186.50	BENT	373.00	373.00
1	FRONT BUMPER TOWING COVER	SERVICEABLE	29.00	-
1	FRONT BUMPER MOULDING CENTRE UPPER	CUT	368.50	368.50
1	FRONT BUMPER MOULDING	NOT NECESSARY	93.60	-
1	FRONT BUMPER LOWER STIFFNER	BENT	285.10	285.10
1	FRONT BUMPER LOWER GRILLE	BROKEN	365.30	365.30
1	FRONT BUMPER LOWER MOULDING	CUT / DISTORTED	127.60	127.60
1	FRONT BUMPER LIP	NOT NECESSARY	35.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$35.00	BROKEN	70.00	70.00
2	FRONT BUMPER BRACKET (LH/RH) @\$28.00	SERVICEABLE	56.00	-
2	FRONT BUMPER RETAINER MOUNTING (LH/RH) @\$65.30	NOT NECESSARY	130.60	-
10	FRONT BUMPER CLIPS	NECESSARY	25.00	25.00
2	FRONT BUMPER GRILLE (LH/RH)@\$186.90	O/S CUT / N/S NOT NECESSARY	373.80	186.90
2	FRONT BUMPER AIR DUCT (LH/RH) @\$153.80	NOT NECESSARY	307.60	-
1	DAY LIGHT ,LH	NOT NECESSARY	642.50	-

Report Ref No. CC6/CTI22006253/Dya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DAY LIGHT ,RH	NOT NECESSARY	642.50	-
1	BUZZER ASSY -PIEZO (LH)	NOT NECESSARY	388.00	-
1	HEADLAMP SUPPORT PANEL ASSY	CRACKED / BROKEN	1,139.30	1,139.30
2	HEADLAMP (LH/RH) @\$3987.30	CRACKED / BROKEN	7,974.60	4,220.60
2	HORN UNIT (LH/RH) @\$72.80	SERVICEABLE	145.60	-
1	RADIATOR INVERTER	BENT / PUNCTURE	884.80	884.80
1	RADIATOR	BENT / PUNCTURE	710.50	710.50
1	RADIATOR FAN BLOWER MOTOR ASSY	BROKEN	1,459.60	1,459.60
2	RADIATOR AIR GUARD (LH/RH) @\$76.40	SERVICEABLE	152.80	-
2	RADIATOR AIR GUARD ,UPR (LH/RH) @\$127.50	SERVICEABLE	255.00	-
1	AIRCON CONDENSER	BENT / PUNCTURE	663.60	663.60
1	BOOT LID	BENT / DENTED	2,549.70	2,549.70
1	BOOT LID RUBBER	NECESSARY / TORN	187.40	187.40
2	BOOT LID HINGE (LH/RH) @\$71.30	NOT NECESSARY	142.60	-
2	BOOT LID ABSORBER (LH/RH) @\$86.70	NOT NECESSARY	173.40	-
1	BOOT LID LOCK UPPER	DAMAGED	224.00	224.00
1	BOOT LID 'H' EMBLEM	NECESSARY	28.00	28.00
1	EMBLEM -HYBRID	NECESSARY	24.30	24.30
1	EMBLEM -LONIQ	NECESSARY	31.30	31.30
1	REAR SPOILER	NOT NECESSARY	665.40	-
2	BOOT LID LAMP (LH/RH)@\$822.00	NOT NECESSARY	1,644.00	-
1	BOOT LID TRIMBOARD	NOT NECESSARY	259.70	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOT LID TRIMBOARD CENTRE	NOT NECESSARY	159.60	-
1	BOOT LID GLASS UPPER MOULDING	NOT NECESSARY	186.30	-
1	BOOT LID GLASS LOWER MOULDING	NOT NECESSARY	145.20	-
1	REAR BUMPER	CRACKED / BROKEN	459.40	459.40
1	REAR BUMPER REINFORCEMENT	CRACKED / BROKEN	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$188.10	BENT	376.20	376.20

Report Ref No. CC6/CTI22006253/Dya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ANTENNA ASSY -SMARTK OUTER	MTG BROKEN	689.50	689.50
1	REAR BUMPER CENTRE MOULDING ASSY	BROKEN	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	MTG BROKEN	155.00	155.00
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
2	REAR BUMPER SIDE RETAINER (LH/RH) @\$85.80	NOT NECESSARY	171.60	-
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE	DISLODGE	123.85	123.85
2	REAR BUMPER SIDE UNDER (LH/RH) @\$123.10	DEFORMED / BROKEN	246.20	246.20
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$82.90	NOT NECESSARY	165.80	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	98.80	-
1	LICENCE LAMP	NOT NECESSARY	193.53	-
1	LICENCE LAMP WIRE	NOT NECESSARY	135.80	-
2	TAIL LAMP (LH/RH) @\$935.40	NOT NECESSARY	1,870.80	-
2	TAIL LAMP QUARTER PANEL (LH/RH) @\$208.90	NOT NECESSARY	417.80	-
1	REAR PANEL	DENTED	532.00	532.00
1	ANTENNA ASSY -TRUNK	NOT NECESSARY	689.50	-
1	REAR PANEL GARNISH	DEFORMED	346.80	346.80
1	REAR TRAY TOOLS BOX RH	NOT NECESSARY	675.30	-
1	REAR TRAY TOOLS BOX LH	NOT NECESSARY	693.20	-
1	REAR TRAY LUGGS CENTER	NOT NECESSARY	354.20	-
1	EXHAUST PIPE INSULATOR	NOT NECESSARY	235.00	-
1	EXHAUST SILENCER	NOT NECESSARY	943.50	-
2	EXHAUST PIPE HANGER @\$29.20	NOT NECESSARY	58.40	-
1	ELECTRONIC CLUTCH PUMP (ADDITIONAL)	CRACKED	4,386.50	4,386.50
	LESS 20% DISCOUNT		-9,660.39	-6,120.60
			38,641.54	24,482.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) }	DISTORTED	25.00	45.00
1	FRONT NO PLATE TRIM COVER (SN) }	CRACKED / DEFORMED	30.00	-
1	COOLANT (SN)	NOT NECESSARY	45.00	-
1	REVERSE CAMERA ASSY (SN)	NOT NECESSARY	983.20	-

Report Ref No. CC6/CTI22006253/Dya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID COMFORT LOGO & TEL NO.STICKER (SN)	NECESSARY	35.00	35.00
1	BOOT LID COMFORT CABLINK TEL NO. STICKER (SN)	NOT FITTED	30.00	-
1	REAR NO PLATE +TRIM COVER (SN)	CRACKED / DEFORMED	45.00	45.00
2	REAR WINDSCREEN SEALANT @\$46.00 (SN)	NECESSARY	92.00	92.00
1	REAR BUMPER RUBBER MAT (SN)	NOT FITTED	50.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	180.00	180.00
1	SPARE TYRE PANEL TOP COVER SILICON (SN)	NOT NECESSARY	250.00	-
1	CLUTCH FLUID (SN) (ADDITIONAL)	SERVICEABLE	85.00	-
			1,850.20	397.00
	LABOUR			
	PANEL BEATING.		2,200.00	900.00
	SPRAY PAINTING CHARGE.		2,000.00	900.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX REAR WINDSCREEN GLASS .		240.00	120.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	40.00
	REMOVE/REFIX EXHAUST PIPE .	NOT NECESSARY	80.00	-
	REMOVE/REFIX RADIATOR .		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS .		130.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			5,690.00	2,310.00
GRAND TOTAL			46,181.74	27,189.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				24,400.00

Report Ref No. CC6/CTI22006253/Dya3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4531S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4531S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4531S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

