

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT22001850	Page	1
Registration No	: SMX278K	Date	: 29. Jun 2022		
Chassis No	: JHMRU1810JX202809	Customer No.	: WZI007		
Model	: HRV DX-SIN CVT YM 2018	Svc Advisor	: LEE CHEN SIN		
Owner's Name	: NG HUI ZHEN	Engine No	: L15B5672817		
Ins Policy No.	:	Date Time	: 29. Jun 2022 9:46:44 AM		
Date of Accident	: 27/6/2022	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NG HUI ZHEN OWNER INSURER: TOKIO MARINE INSURANCE (SG) LTD ACC DATE: 27/06/2022 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: GBK4685R						
75722-T7W-A01	EMBLEMRR.	1	15.20	25	11.40	0.80	12.20
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	16.60	25	12.45	0.87	13.32
33502-T7A-J31	LAMP UNIT,R.	1	428.30	25	321.22	22.49	343.71
04717-T7A-J00ZZ	FACE,R.RR.BUMPER CORNER	1	100.40	25	75.30	5.27	80.57
71593-T7A-J00	SPACER,R.RR.BUMPER SIDE	1	18.00	25	13.50	0.95	14.45
71501-T7B-000	FACE RR.BUMPER	1	829.60	25	622.20	43.55	665.75
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	178.50	25	133.87	9.37	143.24
66100-T7A-300ZZ	PANEL COMPRR.	1	397.90	25	298.42	20.89	319.31
84610-T7A-J01ZA	BASE COMPR.TRUNK SIDE LINING	1	156.80	25	117.60	8.23	125.83
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	46.80	25	35.10	2.46	37.56
04636-T7A-310ZZ	PANEL SET,R.RR.OUTSIDE	1	655.20	25	491.40	34.40	525.80
74410-T7B-003	PROTECTOR,R,RR.WHEEL ARCH	1	187.20	25	140.40	9.83	150.23
75450-SAA-013	OUTLETRR AIR	1	26.90	25	20.17	1.41	21.58
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
					Sum Item	2630.28	184.13
							2,814.41
BOSUN	SUNDRIES	1	100.00	10	90.00	6.30	96.30

Printed on 30/6/2022 9:56:21 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT22001850	Page	2
Registration No	: SMX278K	Date	: 29. Jun 2022	Customer No.	: WZI007
Chassis No	: JHMRU1810JX202809	Svc Advisor	: LEE CHEN SIN	Engine No	: L15B5672817
Model	: HRV DX-SIN CVT YM 2018	Date Time	: 29. Jun 2022 9:46:44 AM	Surveyor Name	:
Owner's Name	: NG HUI ZHEN	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 27/6/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	10	252.00	17.64	269.64
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	600.00	10	540.00	37.80	577.80
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	500.00	10	450.00	31.50	481.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	350.00	10	315.00	22.05	337.05
BOJSE	BODY JOINT SEALANT. END PANEL	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT. RR FENDER	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	350.00	10	315.00	22.05	337.05
BKRP22M	CUT & RENEW RR PANEL, GUTTER AND RR FENDER.	1	5500.00	10	4950.00	346.50	5296.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00	10	3150.00	220.50	3370.50
Sum Labor					10262.00	718.34	10,980.34

Survey By

Date & Time

Excess

Status

Signature

Total Amount 12,892.28 902.47 13,794.75**Total (Inclusive of GST)** **13,794.75****Printed on 30/6/2022 9:56:21 AM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.