

HONDA

KAH MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)

and Body Repair

65 6841 3838

Website: www.honda.com.sg

24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMX278K
Chassis No : JHMRU1810JX202809
Model : HRV DX-SIN CVT YM 2018
Owner's Name : NG HUI ZHEN
Ins Policy No :
Date of Accident : 27/6/2022

Document No. : SQT22001850
Date : 29. Jun 2022
Customer No. : WZI007
Svc Advisor : LEE CHEN SIN
Engine No : L15B5672817
Date | Time : 29. Jun 2022 9:46:44 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NG HUI ZHEN OWNER INSURER: TOKIO MARINE INSURANCE (SG) LTD ACC DATE: 27/06/2022 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: GBK4685R						
75722-T7W-A01	EMBLEMRR. <i>re</i>	1	15.20	25	11.40	0.80	12.20
75725-T8N-T00	EMBLEM,RR. I-VTEC <i>re</i>	1	16.60	25	12.45	0.87	13.32
33502-T7A-J31	LAMP UNIT,R. <i>CM</i>	1	428.30	25	321.22	22.49	343.71
04717-T7A-J00ZZ	FACE,R,RR.BUMPER CORNER <i>de</i>	1	100.40	25	75.30	5.27	80.57
71593-T7A-J00	SPACER,R,RR.BUMPER SIDE <i>re</i>	1	18.00	25	13.50	0.95	14.45
71501-T7B-000	FACE RR.BUMPER <i>see</i>	1	828.60 <i>492.50</i>	25 <i>36.37</i>	622.20	43.55	665.75
91505-TM8-003	CLIP,BUMPER <i>re</i>	10	2.30	25	17.25	1.21	18.46
33505-T7A-J01	REFLECTOR ASSYR,RR. <i>? X m</i>	1	178.50	25	133.87	9.37	143.24
66100-T7A-300ZZ	PANEL COMPR. <i>repar XR</i>	1	397.90	25	298.42	20.89	319.31
84610-T7A-J01ZA	BASE COMPR.TRUNK SIDE LINING <i>X m</i>	1	156.80	25	117.60	8.23	125.83
84640-T7A-J01ZA	LINING ASSYRR.PANEL <i>X m</i>	1	46.80	25	35.10	2.46	37.56
04636-T7A-310ZZ	PANEL SET,R,RR.OUTSIDE <i>st</i>	1	655.20	25	491.40	34.40	525.80
74410-T7B-003	PROTECTOR,R,RR.WHEEL ARCH <i>see</i>	1	187.20	25	140.40	9.83	150.23
75450-SAA-013	OUTLETRR AIR <i>CM</i>	1	26.90	25	20.17	1.41	21.58
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>re</i>	1	320.00		320.00	22.40	342.40
					Sum Item	2630.28	184.13
						1792.46	2,814.41
BOSUN	SUNDRIES	1	100.00	30	90.00	6.30	96.30

Printed on 30/6/2022 9:56:21 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)

and Body Repair

65 6841 3838

Website: www.honda.com.sg

24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMX278K
Chassis No : JHMRU1810JX202809
Model : HRV DX-SIN CVT YM 2018
Owner's Name : NG HUI ZHEN
Ins Policy No :
Date of Accident : 27/6/2022

Document No. : SQT22001850 Page 2
Date : 29. Jun 2022
Customer No. : WZ1007
Svc Advisor : LEE CHEN SIN
Engine No : L15B5672817
Date | Time : 29. Jun 2022 9:46:44 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML021	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00 250	10	225 252.00	17.64	269.64
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	600.00 500	10	450 540.00	37.80	577.80
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	500.00 400	10	360 450.00	31.50	481.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	350.00 250	10	225 315.00	22.05	337.05
BOJSE	BODY JOINT SEALANT. END PANEL	1	100.00	X	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT. RR FENDER	1	100.00	80	80 100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	350.00 250	10	225 315.00	22.05	337.05
BKRP22M	CUT & RENEW RR PANEL, GUTTER AND RR FENDER.	1	550.00 350	10	315 495.00	346.50	5296.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	350.00	10	315 350.00	220.50	3370.50
			2080	Sum Labor	10262.00	718.34	10,980.34
					6684.50		

Survey By : Rasul - Hp 90010068
Date & Time : 12/07/22 @ 1555
Excess :
Status : 8 days
Signature : Per
Very before print

Total Amount 12,892.28 902.47 13,794.75
Total (Inclusive of GST) 13,794.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 30/6/2022 9:56:21 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

1792.46
6684.50
8476.96

8 days