

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22006258/KQY3Q2**Date:** 28/04/2023**REFERENCE**

Insured/Claimant: HO KANG WEN Policy No: DMPCSNW00093892200

Date of Loss: 26/06/2022 Nature of Claim: OD Claim No: SNM22D204559/C01/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMF8346P**

Make & Model: BMW X4, 3.0 xDrive35i (A)

Engine No: 03709296N55B30A

Reg. Date: 07/10/2015 (Man. Year: 2015)

Chassis No: WBAXW520700F90320

Colour: Metallic Pearl White

Odometer: 108217 km

Engine Capacity: 2979 cc

Market Value/New Car Price: S\$109,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R19

Rear Tyre Size: 275/40 R19

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,971.65	19,437.00	534.65	2.68
Miscellaneous Items	230.00	230.00	0.00	0.00
Labour	1,502.64	1,430.16	72.48	4.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,704.29	21,097.16	607.13	2.80
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	21,704.29	20,597.16	1,107.13	5.10
+ GST 7.00/8.00% (S\$)	1,519.30	1,647.77	-128.47	-8.46
Nett Amount (S\$)	23,223.59	22,244.93	978.66	4.21

INSPECTION

Date of Assignment: 30/06/2022 Present Location:

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 30/06/2022 Inspected At:

10 ANG MO KIO IND PARK 2A
#01-04 ANG MO KIO AUTOPOINT . SINGAPORE
568047

Estimated Period of Repair: 8.0 days

Repairer: Cheng Hoe Motor Pte Ltd (Yishun)

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2023)
Parts:	M1-SUV	BMW X4 3.0 xDrive35i (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF8346P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS		19,971.65 F	*19,437.00 F
F=Franchise part.						
Total Parts (S\$)					19,971.65	19,437.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	SUNDRY	100.00	100.00
2	1	TOTAL OF EXTRAS	130.00	130.00
Sub Total (\$\$)			230.00	230.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL OF LABOUR	New	682.50	623.00
2	TOTAL PAINT INCLUDING MATERIAL	New	820.14	807.16
Gross Labour Cost (\$\$)			1,502.64	1,430.16

Report was unsubmitted during this print-out.

< END OF ESTIMATES >