

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 01 Jul 2022

Preliminary Advice

Vehicle No	: SMF8346P	Accident Date	: 26/06/2022
Make	: BMW X4	Policy No.	: DMPCSNW00093892200
Assignment Date	: 30/06/2022	Excess	: S\$500.00
Date of Inspection	: 30/06/2022	Est. Duration of Repair	: 8
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 21,704.29
Revised Amount	:S\$ 11,173.94
Check Items (Estimated)	:S\$ 10,139.20
Total	:S\$ 21,313.14

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 109,000.00
COE / PARF Rebate	:S\$ 73,117.00

Salvage Value	:S\$
Margin for Repair	:S\$ 35,883.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART PART BASIS DUE TO NO 2ND HAND PARTS AVAILABLE.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.