



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|---|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | Ref: CS/SMR22006261/Aqy3m4 Date: 25/11/2022 Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHB 581J | Veh. Inspected | SLJ 2511J |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | TAX/06/22/2078 | Excess (\$) | 0.00 |
| Assign From | HUA YEN | Assign Date | 30/06/2022 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | HONDA SHUTTLE | c.c | 1496 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | GP71043591 | Colour | BLACK |
| Odometer | 282570 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 185/60 R15 | ARIVO | 6 mm |
| L/H Front Tyre | 185/60 R15 | ARIVO | 6 mm |
| R/H Rear Tyre | 185/60 R15 | ARIVO | 6 mm |
| L/H Rear Tyre | 185/60 R15 | ARIVO | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 28/06/2022 | Inspection Date | 30/06/2022 |
| Survey held at | XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | |