



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI22006263/Kqy3e2

Date: 20/10/2022

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 4387S	Veh. Inspected	SND 8761Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10016035 /KY	Excess (\$)	0.00
Assign From	MAYBIE CHUA	Assign Date	30/06/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY (A)	c.c	2487
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	JTNBA3HKX03005486	Colour	METALLIC SILVER
Odometer	3884 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	9 mm
L/H Front Tyre	215/55 R17	MICHELIN	9 mm
R/H Rear Tyre	215/55 R17	MICHELIN	9 mm
L/H Rear Tyre	215/55 R17	MICHELIN	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/06/2022	Inspection Date	12/07/2022
Survey held at	TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**